

RUI

Not withered
L1 Smg 85050k
Return After Paint
5 days

Adjustment of Spare Parts Costs for Repairs SMN 5618H

Item	Qty	Vehicle parts description		S
1	1	Rear upper bumper 76270	Rm	800.00 ✓
2	2	Rear bumper side retainer LH & RH	Rm	150.00 X
3	1 set	Rear bumper fasteners	Rm	45.50 ✓
4	2	Rear bumper reflector LH & RH	Rm	180.00 X
5	2	Side bumper LH & RH	Rm	780.00 X
6	1	Tailgate	Rm	900.00 ✓
7	1	Tailgate Honda emblem	Rm	68.00 ✓
8	1	Tailgate vezel emblem	Rm	68.00 ✓
9	1	Tailgate weatherstrip	0111/11	220.00 5081m
10	1 set	Tailgate inner trim fasteners	Rm	55.00 ✓
11	1	Tailgate inner board	mgm	380.00 ✓
12	2	Tailgate lamp LH & RH 0595	Rm	1880.00 ✓
13	2	Tailgate number plate lamp LH & RH	Rm	130.00 X
14	1	Rear windscreen wiper	Rm	65.00 X
15	1	Exhaust pipe	Rm	780.00 X
16	1	Rear end panel	Rm	450.00 ✓
17	1	Rear end panel top garnish	mgm	190.00 ✓
18	1 set	Rear end panel top garnish fasteners	Rm	40.00 ✓
19	1	Windscreen moulding 112	Rm	185.00 ✓
20	1	rear boot tray	Rm	300.00 X
21	1	Tailgate cylinder lock	Rm	95.00 X
22	2	bootlid rubber stopper	Rm	35.00 X
23	1	rear exhaust heat insulator	Rm	100.00 X
24	1 set	rear exhaust heat insulator fastener	Rm	28.00 X
25	1	rear wheel arch LH & RH	mgm	450.00 Lt C166.
26	1	Tailgate inner lock	Rm	250.00 ✓
27	2	rear fender inner trim board LH & RH	Rm	1380.00 N1 cm Lt C336.
28	1	spare tyre panel	Rm	750.00 X
29	1	spare tyre panel board	Rm	385.00 X
30	1	tailgate center garnish 312	mgm	355.00 ✓

11494.50

Less 20%

2298.9

9195.60

Special nett item

1	1	Rear number plate w casing	Rm	60.00 X
2	1	Rear windscreen sealant	Rm	60.00 401m
3	1	End panel sealant	Rm	60.00 301m
	1	spare tyre panel sealant	Rm	60.00 X
4	1	Rear camera	Rm	300.00 X
5	1	Reverse sensor	Rm	200.00 ✓

Total parts

740.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before the spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Adjustment of Labour Costs for Repairs

Spraying of affected areas	1000.00	6801
Carry out body cavity preservation	100.00	601
To remove & replaced damaged parts including straightening & repositioning replacement parts & panel beat	1000.00	8001
Remove & refix rear windscreen	150.00	1201
Check wiring	60.00	201
Remove & refix reverse sensor	80.00	501
Remove & refix rear camera	80.00	401
Remove & refix tailgate components	80.00	601
Remove & reinstall rear boot upholstery	80.00	601
Remove & refix exhaust for checking/repair ~ ~	80.00	X
Total labour	2710.00	

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged parts during resurvey
• Parts prices are subject to confirmation
• This party survey is on a "Without prejudice" basis
• No modification(s) is allowed
• Any modification(s) must be resurveyed and
• Not to final approval from Insurance Company