

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jenny Lew

Date: 29 Dec 2022

Preliminary Advice

Vehicle No	: XE253B	Accident Date	: 10/12/2022
Make	: ISUZU FVR34P	Policy No.	: DMCVSNW00001132206
Assignment Date	: 15/12/2022	Excess	: S\$2,000.00
Date of Inspection	: 16/12/2022	Est. Duration of Repair	: 0
Inspection At	: AUTO INSURE PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	
Revised Amount	:S\$	
Check Items (Estimated)	:S\$	0.00
Total	:S\$	

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	56,000.00
COE / PARF Rebate	:S\$	11,297.00
Salvage Value	:S\$	
Margin for Repair	:S\$	44,703.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Pending repair cost from Repairer.