## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909 From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Jenny Lew Date: 29 Dec 2022

# **Preliminary Advice**

Vehicle No : XE253B Accident Date : 10/12/2022

Make : ISUZU FVR34P Policy No. : DMCVSNW00001132206

Date of Inspection : 16/12/2022 Est. Duration of Repair : 0

Inspection At : AUTO INSURE PTE LTD

### Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ TOTAL LOSS
Revised Amount :S\$ TOTAL LOSS
Check Items (Estimated) :S\$ 0.00

Total :S\$

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value :S\$

Pre-Accident Value :S\$ 56,000.00 COE / PARF Rebate :S\$ 11,297.00

Salvage Value :S\$

Margin for Repair :S\$ 44,703.00

### Remarks

(	)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
		Kindly let us have your authorisation.

- ( X ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Vehicle Recommend Total Loss.