

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jenny Lew

Date: 15 Mar 2023

Preliminary Advice

Insured Vehicle No	: XE253B	Accident Date	: 10/12/2022
TP Vehicle No	: YN4692G	Assignment Date	: 15/12/2022
Make	: MITSUBISHI CANTER	Est. Duration of Repair	: 4
Date of Inspection	: 15/12/2022		
Inspection At	: THIAM HENG HUAT PTE LTD (SIN MING) 176 SIN MING DRIVE, #05-14 SINGAPORE 575721		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,294.00
Revised Amount	:S\$	5,026.40
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,026.40
 Lump Sum Repair	 :S\$	 4,000.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.