

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SH7567T

Make : HYUNDAI

Model : IONIQ

Date: 01/12/2022

Insurance: INCOME

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			SCR \$459.40 ✓
10	REAR BUMPER CLIPS			NEC \$22.00 ✓
1	REAR BUMPER CENTRE MOULDING ASSY			? \$451.25 ✓ LUT
1	REAR BUMPER REINFORCEMENT			? \$394.80 XNN
2	REAR BUMPER REINFORCEMENT BRACKET LH RH		\$138.10	? \$276.20 XNN
1	ANTENNA SMARTKEY			MAX? \$40.50 XNN
1	REAR BUMPER FOG LAMP			FR \$201.50 ✓
	SUB TOTAL		1134.15	\$1,845.65
	LESS 20%		226.83	\$369.13
	DISCOUNTED TOTAL		907.32	\$1,476.52
	RENEW ADVERTISEMENT STICKER			NEC \$200.00
	REAR NUMBER PLATE WITH TRIM COVER		49.5 -10%	maxing \$55.00 nec
	REAR BUMPER REVERSE SENSOR		162 -10%	FR \$180.00
	REAR BUMPER RUBBER MAT			NEC \$50.00
		NETT		\$485.00
	Labour Charge			
	PANEL BEATING			\$400.00 350
	SPRAY PAINTING CHARGE			\$300.00 250
	REMOVE/REFIX REVERSE SENSOR			\$80.00 30
	TOTAL LABOUR			\$780.00
	ESTIMATE TOTAL		20% - 630 404 \$1600	\$2,741.52

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

By irfan 2/12/22 T = 1998.82
3 days 20% = 399.76

L/S

FT = 1599.06

251600