



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INCOME INSURANCE LTD 75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557 ATTN: MARCUS XIAO			Ref: CS3/INC22008150/Rqy3e2-1 Date: 14/03/2023 Code: INC	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	FBQ 1990Y	Veh. Inspected	SJT 3166L
	Policy No.		Coverage (\$)	0.00
	Claim No.	MT/1185553-002	Excess (\$)	0.00
	Assign From		Assign Date	16/12/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA COROLLA ALTIS CL 1.6	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	MR053REH104546296	Colour	GREY
	Odometer	277267 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	GRENLANDER	6 mm
	L/H Front Tyre	205/55 R16	GRENLANDER	6 mm
	R/H Rear Tyre	205/55 R16	GRENLANDER	6 mm
	L/H Rear Tyre	205/55 R16	GRENLANDER	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	21/08/2022	Inspection Date	24/08/2022
	Survey held at	MILLION AUTO SERVICE 4 PENJURU PLACE #01-12 2.8 PENJURU TECH HUP SINGAPORE 608782		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	