



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: LK001250

Date: 07th Feb 2023

Our Ref: CS1/SGK22012583/Dny3e2

M/s Tokio Marine Insurance Singapore Ltd

C/O Sedgwick Singapore Pte Ltd

30 Cecil Street, Level 12

Prudential Tower

Singapore 049712

(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SMU 6831P
INSURED VEHICLE: PUBLIC LIABILITY
ACCIDENT DATE: 04/09/2021**

We thank you for your instruction on 13/12/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SMU 6831P from M/s TTS Eurocars Pte Ltd.
- b) Colour damaged vehicle photographs of SMU 6831P.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SMU 6831P
Make & Model	: B.M.W. 320I LED HL
Year of Registration	: 2020
Chassis Number	: WBA5F32050FJ03895
Engine Capacity	: 1998 cc



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

2. Our finding is that the repair cost of \$48,972.80 (before GST) quoted by M/s TTS Eurocars Pte Ltd is fair & reasonable.

3. We recommend that the repairs of the entire damage require about 25 (Twenty-Five) working days to complete.

Vehicle Inspected By:

ANG BRYAN TANI
Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.