PRE INVOICE

BUDGET DIRECT INSURANCE 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTER SINGAPORE 239924

DOCUMENT NO: IN21-102170 DATE

: 18.01.2022

Vehicle No: SMU6831P

Staff ID : EULINDRA

BMW 320i

Mileage: 0 JOB NO : T21-102170

		9820 9820				
	Description	quantity U	Unit	Price A	Amount	\supset
1	SEAT BELT	1			\$320.00	you
2	SEAT BELT	1			\$320.00	Dan
3	SEAT BELT LOWER STRAP	2		\$280.00	\$560.00	(mt
4	FLOOR MAT SET COMPLETE	1		Can	,	
5	REGULATING LAMBDA PROBE	1		Co		
6	CATALYTIC CONVERTER	1		Cov	,	
7	GASKET RING	1		Nec		
8	AXLE OIL	1		Nec		
9	PULSE GENERATOR DSC	2		\$198.00	\$396.00	Day
10	PULSE GENERATOR DSC REAR	2		\$180.00	\$360.00	Dan
11	FRONT BUMPER CABLE	1			\$234.00	Dan
12	CABLE SET END	1			\$255.00	
13	FRONT LEFT REPAIR WIRING	1			\$650.00	Dan
14	FRONT RIGHT REPAIR WIRING	1			\$720.00	Dar
15	REAR REPAIR WIRING SET	1		Short	ed \$1,260.00	
16	SET CABLE REAR BUMPER	1		Co	\$230.00	
17	CABLE ELECTRO PARKING BRAKE	1			rited \$74.00	
18	CABLE ELECTRO PARKING BRAKE	1		Shor	\$74.00	
19	DOOR CABLE HARNESS	1		Shor	Jed \$370.00	
20	DOOR CABLE HARNESS	1		Shor	ted \$370.00	
21	REAR DOOR WIRING HARNESS	1			\$335.00	
22	REAR DOOR WIRING HARNESS	1		_	\$335.00	
23	WIRING SET SEAT LEFT	1			\$85.00	Dan
24	WIRING SET SEAT RIGHT	1			\$85.00	Dw
25	BATTERY LEAD POSITIVE UND	1			\$560.00	Din
26	BATTERY CABLE (PLUS POLE)	1		Cor	\$235.00	
27	MAIN WIRING HARNESS	1		Shortes	\$6,000.00	
28	AUDIO WIRING HARNESS	1		Shorted	\$1,170.00	
29	SENSOR WIRE SMART OPENER	1			\$45.00	Da
30	SENSOR WIRE SMART OPENER	1			\$51.00	Dun
31	WIRING HARNESS MOTOR SENSOR 1	1		COV	\$600.00	
32	WIRING HARNESS MOTOR SENSOR 2	1		Con	\$600.00	
33	WIRING HARNESS ENGINE IGNITION	1		Cor	\$600.00	
34	WIRING HARNESS ENGINE VALVE SERV	1		(0	180.00	
35	WIRING HARNESS ENGINE GEARBOX MO	1		Cov	\$460.00	
36	SUBWOOFER	1		Def	\$450.00	
37	SUBWOOFER	1		Def	\$450.00	
38	FLOOR TRIM FRONT	1		Soaked	\$990.00	
				Sough		

39 40 41	FLOOR TRIM REAR INSERT FRONT LEFT INSERT FRONT RIGHT	1 1 1	Soaked	\$940.00 \$23.00 \$23.00	2~
42	RADAR SENSOR	malfunction 2	\$1,240.00 \$2	2,480.00	
43	ELECTRIC FAN	1		\$220.00	
44	SEAT MODULE ECU	1		\$500.00	mal
45	AUTO OILPAN W/LIT	1		\$80.00	D
46	BMW OIL FILTER	1		\$18.00	
47	BMW COOLANT ANTI-FREEZE	1	Nec	\$10.00	
48	AUTO FLUID (1 LITRE)	6	\$18.00 Nec		
49	BMW CONTROL UNIT FOR FUEL PUMP	1	corroded		
50	RIVET	6	\$4.00 Nec		
51	BRAKE PAD	1	Corroded	\$185.00	
52	BRAKE PAD WEAR SENSOR, FR	1	Con	\$32.00	
53	REAR PAD	1		\$160.00	
54	BRAKE DISK	2	\$125.00 Rusty	\$250.00	
55	BRAKE PAD SENSOR, REAR	1	Con	\$32.00	
56	BMW BRAKE DISC FR	2	\$115.00 Rusty		
57	BODY DOMAIN CONTROLLER	1		1,350.00	
58	BMW STARTER MOTOR	1		\$958.00	Dar
59	AUTO FLUID (1 LITRE)	8	. 1	\$144.00	
60	BMW CONTROL UNIT	1	Corroded \$	1,030.00	
61	BMW SENSOR HIGH PRESSURE	1		00.882	
62	BMW SENSOR DOOR	1		\$165.00	_
63	BMW CARRIER	1			& Din
64	BMW DOOR LOCK REAR LH	1		\$350.00	
65	BMW LAMP	1	Blown	\$31.00	0. 1
66	MEMORY SEAT	1	\$4	4,800.00	nal
			Parts Total \$3"	7.236.95	
				7,236.95 1,861.85	
			Add 5% \$1	7,236.95 1,861.85 9,098.80	
			Add 5% \$1	1,861.85	
	SPECIAL NETT ITEMS	1	Add 5% \$1	1,861.85 9,098.80	
1	SPECIAL NETT ITEMS NUMBER PLATE		Add 5% \$1	1,861.85	Du
1 2			Add 5% \$1 Total \$39	\$35.00 \$69.00	rus
	NUMBER PLATE		Add 5% \$1 Total \$39	\$35.00 \$69.00 \$110.00	rus
2	NUMBER PLATE ENGINE OIL (LIQUI MOLY 5 LITRES)	1	Add 5% \$1 Total \$39	\$35.00 \$69.00	rus
2	NUMBER PLATE ENGINE OIL (LIQUI MOLY 5 LITRES) TUNAP 994 A/C SYSTEM CLEANER		Add 5% \$1 Total \$39	\$35.00 \$69.00 \$110.00	rus
2 3	NUMBER PLATE ENGINE OIL (LIQUI MOLY 5 LITRES) TUNAP 994 A/C SYSTEM CLEANER Labour		Add 5% \$1 Total \$39	\$35.00 \$69.00 \$110.00 \$214.00	rus
2	NUMBER PLATE ENGINE OIL (LIQUI MOLY 5 LITRES) TUNAP 994 A/C SYSTEM CLEANER	1	Add 5% \$1 Total \$39	\$35.00 \$69.00 \$110.00	rus
2 3	NUMBER PLATE ENGINE OIL (LIQUI MOLY 5 LITRES) TUNAP 994 A/C SYSTEM CLEANER Labour		Add 5% \$1 Total \$39	\$35.00 \$69.00 \$110.00 \$214.00	rus
2 3	NUMBER PLATE ENGINE OIL (LIQUI MOLY 5 LITRES) TUNAP 994 A/C SYSTEM CLEANER Labour Wiring connection & check To remove & refix radiator, condenser, A/C ground conduct pressure test, check for leaks, vaccum refill.	as, 1	Add 5% \$1 Total \$39 SN Total	\$35.00 \$69.00 \$110.00 \$214.00	rus
2 3	NUMBER PLATE ENGINE OIL (LIQUI MOLY 5 LITRES) TUNAP 994 A/C SYSTEM CLEANER Labour Wiring connection & check To remove & refix radiator, condenser, A/C gronduct pressure test, check for leaks, vaccum refill. Labour charges to repair/replace front bumper	as, 1	Add 5% \$1 Total \$39 SN Total	\$35.00 \$69.00 \$110.00 \$214.00 \$150.00	rus
2 3	NUMBER PLATE ENGINE OIL (LIQUI MOLY 5 LITRES) TUNAP 994 A/C SYSTEM CLEANER Labour Wiring connection & check To remove & refix radiator, condenser, A/C ground to pressure test, check for leaks, vaccum refill. Labour charges to repair/replace front bumper front bonnet, support panel, chassis extension,	as, 1	Add 5% \$1 Total \$39 SN Total	\$35.00 \$69.00 \$110.00 \$214.00 \$150.00	rus
2 3	NUMBER PLATE ENGINE OIL (LIQUI MOLY 5 LITRES) TUNAP 994 A/C SYSTEM CLEANER Labour Wiring connection & check To remove & refix radiator, condenser, A/C goonduct pressure test, check for leaks, vaccum refill. Labour charges to repair/replace front bumper front bonnet, support panel, chassis extension, 2 front fenders, and all other affected	as, 1	Add 5% \$1 Total \$39 SN Total	\$35.00 \$69.00 \$110.00 \$214.00 \$150.00	rus
2 3	NUMBER PLATE ENGINE OIL (LIQUI MOLY 5 LITRES) TUNAP 994 A/C SYSTEM CLEANER Labour Wiring connection & check To remove & refix radiator, condenser, A/C ground to pressure test, check for leaks, vaccum refill. Labour charges to repair/replace front bumper front bonnet, support panel, chassis extension,	as, 1	Add 5% \$1 Total \$39 SN Total	\$35.00 \$69.00 \$110.00 \$214.00 \$150.00	rus
2 3	NUMBER PLATE ENGINE OIL (LIQUI MOLY 5 LITRES) TUNAP 994 A/C SYSTEM CLEANER Labour Wiring connection & check To remove & refix radiator, condenser, A/C goonduct pressure test, check for leaks, vaccum refill. Labour charges to repair/replace front bumper front bonnet, support panel, chassis extension, 2 front fenders, and all other affected	as, 1	Add 5% \$1 Total \$39 SN Total	\$35.00 \$69.00 \$110.00 \$214.00 \$150.00	rus
2 3	NUMBER PLATE ENGINE OIL (LIQUI MOLY 5 LITRES) TUNAP 994 A/C SYSTEM CLEANER Labour Wiring connection & check To remove & refix radiator, condenser, A/C goonduct pressure test, check for leaks, vaccum refill. Labour charges to repair/replace front bumper front bonnet, support panel, chassis extension, 2 front fenders, and all other affected	as, 1	Add 5% \$1 Total \$39 SN Total	\$35.00 \$69.00 \$110.00 \$214.00 \$150.00	rus
2 3	NUMBER PLATE ENGINE OIL (LIQUI MOLY 5 LITRES) TUNAP 994 A/C SYSTEM CLEANER Labour Wiring connection & check To remove & refix radiator, condenser, A/C goonduct pressure test, check for leaks, vaccum refill. Labour charges to repair/replace front bumper front bonnet, support panel, chassis extension, 2 front fenders, and all other affected	as, 1	Add 5% \$1 Total \$39 SN Total	\$35.00 \$69.00 \$110.00 \$214.00 \$150.00	rus
2 3	NUMBER PLATE ENGINE OIL (LIQUI MOLY 5 LITRES) TUNAP 994 A/C SYSTEM CLEANER Labour Wiring connection & check To remove & refix radiator, condenser, A/C goonduct pressure test, check for leaks, vaccum refill. Labour charges to repair/replace front bumper front bonnet, support panel, chassis extension, 2 front fenders, and all other affected	as, 1	Add 5% \$1 Total \$39 SN Total	\$35.00 \$69.00 \$110.00 \$214.00 \$150.00	rus
2 3	NUMBER PLATE ENGINE OIL (LIQUI MOLY 5 LITRES) TUNAP 994 A/C SYSTEM CLEANER Labour Wiring connection & check To remove & refix radiator, condenser, A/C goonduct pressure test, check for leaks, vaccum refill. Labour charges to repair/replace front bumper front bonnet, support panel, chassis extension, 2 front fenders, and all other affected	as, 1	Add 5% \$1 Total \$39 SN Total	\$35.00 \$69.00 \$110.00 \$214.00 \$150.00	rus

, , ,

4	To replace front parking sensor, conduct programming & calibration	1	\$200.00
5	Remove & refix front bumper sensor	1	\$60.00
6	To conduct ECU programming, check and clear fault codes, restore programme modules	1	\$200.00
7	To remove and refix rear bumper, rear boot, spare tyre board, rear rh fender inner trim, rear lh fender inner trim to facilitate replacement of wire harness and audio harness		\$600.00
8	To remove and refix front driver seat, seat belts and buckle, front passenger seat, seat belt and buckle rear passenger seat, seat belt and buckle to facilitate replacement of main wire harness, seat control module seat belts, buckles, fuel pump control unit under the rear passenger seat, replacement of interior carpet sub woofers.		\$300.00
9	To remove and refix front driver door, front passenger door, rear rh door and rear lh door trims, regulator motor and windows to facilitate replacement of door wire harness, air bag sensor, door lock mechanism		\$320.00
10	To remove and refix rear speaker board to facilitate replacement of main wire harness.		\$200.00
11	To remove and refix roof lining to facilitate replacement of main wiring harness		\$400.00
12	To remove and refix centre console, gear selector lever/ module to facilitate replacement of main wire harness, air bag control module and audio wiring harness.		\$200.00
13	To remove and refix LH & RH, front and rear "A" pillar, "B" pillar and "C" pillar, remove curtain air bag and air bag sensor, seat belt crash sensor, to facilitate replacement of main wire harness.		\$400.00
14	To remove and refix dashboard, glove box, steering wheel, head unit, meter and main screen to facilitate replacement of main wire harness, audio harness, can bus and lin bus(communitations) harness. to acquire access to junction box on front RH and LH wire harness junction towards engine bay.		\$300.00

15	To remove and refix blower motor, clean and sanitize		\$200.00
	blower fan and test motor functionality, remove air con		
	air ducts to clean and sanitize ducting from residual		
	water ingress, perform air con cooling coil cleaning		
	and sanitization, calibration of air flap motors and		
	heater coil.		
16	To remove and and refer and but for him to		
10	To remove and and refix engine bay fuse box, wiper		\$400.00
	garnish, air con filter housing, to facilitate replacement of main wire harness thru access of front lh and rh		
	of main whe namess and access of front in and ri		
17	To remove and refix engine air filter housing, radiator		\$200.00
	spare tank, wiper washer reservoir, brake reservoir		
	to allow access to engine components to replace		
	engine wire harness.		
18	To carry out transmission fluid flushing and actuation	:	\$100.00
	of transmission system.		
19	To replace engine oil and oil filter		\$100.00
.,	10 topiaco orgino or and ori mici	•	\$100.00
20	To remove and refix front brake disc and rotors		\$200.00
	remove residual water in bearings, lubricate and replace		
	brake components, replacement of wheel speed		
	sensor and brake sensor wire.		
21	To remove and refix rear brake disc and rotors,	5	\$200.00
	remove residual water and debris from rear bearings,		
	lubricate bearings and bushings, replacement of		
	wheel speed sensors, rear parking brake actuator		
	sensor cable, rear brake pad, brake disc and brake		
	sensor wire		
22	To remove and replace catalytic converter,		\$80.00
22	up-stream O2 sensors, cleaning of exhaust system		\$60.00
	and removal of excess/residual water in the system.		
	and telloral of process tostedat water in the system.		
23	To carry out SCN coding/ programming of fuel pump	5	\$200.00
	control unit		
24	To carry out SCN coding/ programming of air bag		200.00
	control unit.		
25	To carry out SCN coding/ programming of BCM	e	300.00
23	body control module. Immobilizer	3	5500.00
	oody conitrol module. Illimoonizer		
26	To carry out SCN coding/programming of seat	S	300.00
	control module.		

27	To carry out SCN coding/ programming of head unit control module		\$300.00
28	To perform function check on modules programmed via osciloscope - testing of power supply, communication signal and grounding capabilities.		\$500.00
29	To purchase licensing for navigational software, speech processing software, road map of south east asia, speed limit information, lane departure warning system, pedestrian protection system		\$1,100.00
30	To carry out SCN coding/ programming for rear radar sensors/ control module.		\$200.00
31	To carry out SCN coding/ programming for ESP control module.		\$200.00
32	To carry out SCN coding/programming of dynamic stability program		\$200.00
33	To carry out SCN coding/programming for electical power steering module		\$200.00
34	To carry out SCN coding/programming for electical front headlight module		\$200.00
35	To carry out SCN coding/programming for automated climate control system.		\$200.00
	(\$39,098.80 + \$214 + \$9,660)	Labour Subtotal 7% GST Total	\$9,660.00 \$48,972.80 \$3,428.10 \$52,400.90
* Ack	cnowledgement by Customer *		, 100120
conf	firm that the goods stated in this invoice have		

been received by me in good working order and condition.

I further confirm that all services and /or repair jobs

Stated in this invoice are completed and done to my Satisfaction.

TTS EUROCARS PTE LTD

Name/Signature/NRIC No/Co Stamp (where applicable)

Authorised Signature



383 Sin Ming Drive, TTS Centre, Singapore 575717 Ssles: +65 6842 2222 Admin: +65 6757 0122 After Branch: No.15, Commonwealth Lane, Lot A1, Commonwealth Car Mall, Singapore 149554 Tel: +65 64