

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CC3/AIS22012585/RQY3M4**Date:** 07/02/2023**REFERENCE**

Insured/Claimant: MINTAREDJA SIANTAR @SEAH KONG MIN
Date of Loss: 14/12/2022

Policy No: SP2003537327-01
Nature of Claim: OD

Claim No: 202222008885

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMW5676S**
Make & Model: VOLKSWAGEN PASSAT B8, 1.8 TFSI AT 3G24JZ (A) Engine No: CJS308737
Reg. Date: 27/11/2020 (Man. Year: 2019) Chassis No: WVVZZZ3CZKE124143
Colour: Black Odometer: 15835 km
Engine Capacity: 1798 cc
Market Value/New Car Price: S\$137,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,917.18	2,656.10	261.08	8.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,500.00	2,130.00	1,370.00	39.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,417.18	4,786.10	1,631.08	25.42
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	5,817.18	4,186.10	1,631.08	28.04
+ GST 8.00/8.00% (S\$)	465.37	334.89	130.48	28.04
Nett Amount (S\$)	6,282.55	4,520.99	1,761.56	28.04

INSPECTION

Date of Assignment: 15/12/2022

Date Inspected: 16/12/2022 Inspected At:

Volkswagen Centre Singapore (HQ)
247 Alexandra Road
Singapore 159934

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Feb 2023)
Parts:	143	VOLKSWAGEN PASSAT B8 1.8 TFSI AT 3G24JZ (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMW5676S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR	Bent	2,289.74 FS	*2,289.74 FS
2	1		*DOOR SEAL OUTER BLACK	Necessary	146.02 FS	*146.02 FS
3	1		*ALU-LAMIN.INSULATION	Necessary	31.43 FS	*31.43 FS
4	1		*RHR DOOR LOWER MLDG	Necessary	106.32 FS	*76.55 FS
5	1		*RHR DOOR LOWER MLDG CHROME	Necessary	141.02 FS	*101.53 FS
6	1		*GROMMET 8PIECES	Necessary	15.04 FS	*10.83 FS
7	1		*WINDOW SLOT SEAL BLACK/CH	Not Necessary	187.61 FS	*- FS
Total Parts (S\$)						2,917.18 2,656.10

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR	New	280.00	280.00
2	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
3	LABOUR	New	1,120.00	560.00
4	SPRAY PAINTING	New	1,060.00	530.00
5	TFR DOOR MECH	New	560.00	280.00
Gross Labour Cost (S\$)			3,500.00	2,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >