

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422 / 6745 4422 Fax : 6747- 6720 REG NO 200501102H

LIBERTY INSURANCE PTE LTD

51, Club Street # 03 - 00
 Liberty House
 Singapore 069428
 Tel : 1800-542 3789 / 6328-0611
 Fax : 6224 / 1047

Hui Rong,

Quotation

DATE : 14.12.2022
 VEH NO : SLH1291K
 MODEL : Honda HRV
 D O A : 14.12.2022
 YR REF : YP8255Z

(Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SLH1291K (HONDA HRV)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Number Plate Lamp - LH & RH <i>Abc new</i>	2	122.20 <i>X.</i>
2	Rear Bumper <i>Distorted.</i>	1	492.50 <i>✓</i>
3	Rear Bumper Side Holder - LH & RH <i>Dist.</i>	2	52.80 <i>✓</i>
4	Rear Bumper Reflector - LH & RH <i>Abc new</i>	2	303.60 <i>X.</i>
5	Rear End Panel <i>Distorted</i>	1	397.30 <i>✓</i>
6	Rear End Panel Top Garnish <i>Deband</i>	1	98.20 <i>✓</i>
7	Rear End Panel Buzzer <i>Green</i>	1	87.40 <i>X</i>
8	Rear End Panel Antenna Sensor	1	98.50 <i>+</i>
9	Taillamp - LH & RH <i>At</i>	2	978.40 <i>✓</i>
10	Taillamp Lower Apron - LH & RH <i>RH Deband</i>	2	390.00 <i>185.</i>
11	Tailgate <i>Distorted.</i>	1	878.90 <i>✓</i>
12	Tailgate Lock <i>Jammed.</i>	1	189.40 <i>✓</i>
13	Tailgate Weatherstripe <i>At</i>	1	189.90 <i>✓</i>
14	Tailgate Inner Trim Board <i>cracked.</i>	1	250.50 <i>✓</i>
15	Tailgate Reflector - LH & RH <i>RH. cracked</i>	2	791.00 <i>385.50</i>
16	Tailgate Outer Garnish <i>cracked</i>	1	341.20 <i>✓</i>
17	Tailgate Damper - LH & RH <i>Abc new</i>	2	516.40 <i>X</i>
18	Tailgate Glass Moulding <i>new</i>	1	112.40 <i>✓</i>
19	Tailgate Inner Pull Pocket <i>Deband.</i>	1	34.10 <i>✓</i>
20	Honda Logo <i>?</i>	1	55.90 <i>✓</i>
21	HRV Wording <i>Abc new</i>	1	60.40 <i>✓</i>
22	i-Vtec Wording <i>Abc new</i>	1	62.90 <i>✓</i>
23	Rear Fender Inner Trim Board - LH & RH <i>RH Deband</i>	2	570.00 <i>285.</i>
24	Rear Fender Wheel Arc Garnish - LH & RH <i>Abc new</i>	2	333.00 <i>+</i>
25	Spare Tyre Panel <i>Repair</i>	1	745.90 <i>+</i>
26	Spare Tyre Panel Top Cover <i>Deband</i>	1	299.50 <i>✓</i>
27	Spare Tyre Panel Under Cover <i>Abc new</i>	1	298.40 <i>X.</i>
28	Tools Tray Sponge <i>Abc new</i>	1	305.80 <i>X</i>

Item	Description	Qty	Amt
29	Rear Exhaust Pipe	1	681.20 +
30	Rear Exhaust Pipe Mounting	1	34.90 +
31	Rear Exhaust Pipe Gasket	1	33.50 +

Less 20%

\$	9,806.10
	(1,961.22)
\$	7,844.88

S/NETT ITEMS

1	Rear Number Plate	1 set	\$	30.00 -
2	Rear Number Plate Holder	1	\$	30.00 -
3	Rear Bumper Clips	1 set	\$	30.00 -
4	Reverse Sensor	4	\$	350.00 250.
5	Rear End Panel Top Garnish Clips	1 set	\$	20.00 ✓
6	Rear End Panel Sealant	1	\$	60.00 -
7	Tailgate Inner Trim Board Clips	1 set	\$	30.00 -
8	Tailgate Outer Garnish Clips	1 set	\$	20.00 -
9	Tailgate Glass Sealant	1	\$	60.00 -
10	Rear Fender Inner Trim Board Clips	1 set	\$	60.00 30
11	Rear Fender Arc Garnish Clips	1 set	\$	40.00 x
12	Spare Tyre Panel Under Cover Clips	1 set	\$	30.00 +
13	Rear Camera	1	\$	480.00 380.

Total parts

\$	9,084.88
----	----------

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts	1,500.00 900.
2	To putty & spray up paint works	1,400.00 800.
3	To check wiring	50.00 30
4	To remove reverse sensor	100.00 50
5	To remove rear camera	100.00 50
6	To remove rear video recorder	100.00 50
7	To apply tuff coat	150.00 60.
8	To remove upholstery	150.00 80
9	To remove tailgate glass	180.00 120
10	To transfer tailgate fittings	150.00 80

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
11	To remove rear exhaust pipe	2220	150.00 X.
			4,030.00
Grand Total			\$ 13,114.88

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 7455.84.
L/s: 5850.
OT Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: