

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Douglas Ong Chu Chong

Date: 21 Mar 2023

**Preliminary Advice**

Insured Vehicle No	: XD8450B	Accident Date	: 15/12/2022
TP Vehicle No	: SHC7822M	Assignment Date	: 16/12/2022
Make	: HYUNDAI AE IONIQ HEV FL	Est. Duration of Repair	: 7
Date of Inspection	: 16/12/2022		
Inspection At	: BIFROST AUTO PTE LTD (SIN MING) (HQ) BLK 9 SECTOR C, #01-42 SIN MING INDUSTRIAL ESTATE SINGAPORE 575644		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	24,968.90
Revised Amount	:S\$	14,591.62
Check Items (Estimated)	:S\$	0.00
Total	:S\$	14,591.62

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

**Remarks**

- ( ) The vehicle is economical for repair  
 ( ) The vehicle is not economical for repair  
 ( x ) Part-by-Part repair  
 ( ) Lump Sum repair
- ( x ) The above survey was conducted on a 'without prejudice' basis. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.