

Atty. F&C BY:

REF:

CS/MSG22012589/Dny³**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

7

days

Res.: Yes or No

Lum Sum: _____

3/P

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC7822MYr Regn: Feb / 2020Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Hyundai Ioniqcc 1580Colour: YellowA/C: Insured / Std / NI / NASp. Reading: 337465T/Radio: Insured / Std / NI / NAEng/No: G4LEKU388843C/No: KMHLC851CVL4184289Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front

Rear

R/Bal. S mmR/Bal. S mmL/Bal. S mmL/Bal. S mmD.O.A. 15/12/2022D.O.A. 16/12/2022Survey held at 31/12/2022 Sin MingDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MSG XD84508
20/3/23	To seek mandate.
03/04/23	Inform 31P 14,591.62 with 7 days of rep.
	(Red. \$ 10372.28, 4290)

Date/Time, File Pass to?

1) 3/4/23

Date/Time, File Return to?

2)

Report Format: TP

I series 2 cars 1 P 10



: Prel. Report



: Final Report

Days Of Repair: 7Resurvey No. of Trip: 2

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Inve (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	839G

Vehicle Details

Vehicle No.:	SHC7822M
Vehicle to be Exported:	Yes
Intended Deregistration Date:	31 Dec 2022
Vehicle Make:	HYUNDAI
Vehicle Model:	AE IONIQ HEV FL 1.6 DCT
Primary Colour:	Yellow
Manufacturing Year:	2019
Engine No.:	G4LEKU388843
Chassis No.:	KMHC851CVLU184289
Maximum Power Output:	103.6 kW (138 bhp)
Open Market Value:	\$25,755.00
Original Registration Date:	13 Feb 2020
First Registration Date:	13 Feb 2020
Transfer Count:	0
Actual ARF Paid:	\$13,057.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Feb 2028
PARF Rebate Amount:	\$9,792.00

Intended COE Rebate Details

COE Expiry Date:	12 Feb 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$26,431.00
COE Rebate Amount:	\$16,908.00
Total Rebate Amount:	\$26,700.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 15 Dec 2022

OK

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 16-Dec-22

INSURANCE: MSIG

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHC 7822 M

Description	Qty	List Price	Amount
Boot Lid <i>Dent</i>	1	\$ 2,549.70	\$ 2,549.70
Boot Lid Rubber <i>damaged</i>	1	\$ 187.40	\$ 187.40
Boot Lid Hinge (LH/RH) <i>HW</i>	2	\$ 71.30	\$ 142.60
Boot Lid Absorber (LH/RH) <i>HW</i>	2	\$ 86.70	\$ 173.40
Boot Lid Lock Upper <i>BT / Dam</i>	1	\$ 224.00	\$ 224.00
Boot Lid 'H' Emblem <i>HWC</i>	1	\$ 28.00	\$ 28.00
Emblem-Hybrid <i>HWC</i>	1	\$ 24.30	\$ 24.30
Emblem-Ionic <i>HWC</i>	1	\$ 31.30	\$ 31.30
Rear Spoiler <i>money crack</i>	1	\$ 665.40	\$ 665.40
Third Brake Light <i>broken</i>	1	\$ 385.60	\$ 385.60
BOOT HANDLE <i>HW</i>	1	\$ 31.80	\$31.80
Boot Lid Lamp(LH/RH) <i>money crack</i>	2	\$ 822.00	\$ 1,644.00
Boot Lid Trimboard <i>money crack</i>	1	\$ 259.70	\$ 259.70
Boot Lid Trimboard Clips (10pcs) <i>HWC</i>	1	\$ 11.00	\$ 11.00
Boot Lid Trimboard, Centre <i>HW</i>	1	\$ 159.60	\$ 159.60
Boot Lid Trimboard SIDE (LH/RH) <i>HW</i>	2	\$ 92.50	\$ 185.00
Boot Lid Trimboard REAR <i>HW</i>	1	\$ 124.80	\$ 124.80
Boot Lid Glass, Lower <i>3 machine</i>	1	\$ 584.90	\$ 584.90
Boot Lid Glass Upper Moulding <i>HW</i>	1	\$ 186.30	\$ 186.30
Boot Lid Glass Lower Moulding <i>HW</i>	1	\$ 145.20	\$ 145.20
Rear Bumper <i>crack</i>	1	\$ 459.40	\$ 459.40
Rear Bumper Reinforcement <i>crack</i>	1	\$ 394.80	\$ 394.80
Rear Bumper Reinforcement Bracket (LH/RH) <i>bt o/s H/S SV2</i>	1	\$ 188.10	\$ 376.20
Antenna Assy-SMARTK outer <i>money broken</i>	1	\$ 689.50	\$ 689.50
Rear Bumper Centre Moulding Assy <i>crack money</i>	1	\$ 451.25	\$ 451.25
Rear Bumper Lower Centre Moulding Assy <i>crack money</i>	1	\$ 155.00	\$ 155.00
Rear Bumper Stay <i>HW</i>	1	\$ 138.10	\$ 138.10

✓
✓
X
X
✓
✓
✓
✓
✓
✓
X
✓
✓
✓
X
X
X
✓
X
X
✓
✓
✓
40.50
✓
✓
X

Rear Bumper Side retainer (LH/RH) <i>HH</i>	2	\$ 85.80	\$ 171.60
Rear Bumper Cover Clips <i>Hee</i>	1	\$ 22.00	\$ 22.00
Rear Bumper Under Centre <i>Whole mounting</i>	1	\$ 123.85	\$ 123.85
Rear Bumper Side Under(LH/RH) <i>HH</i>	2	\$ 123.10	\$ 246.20
Rear Bumper Reflector Lamp(LH/RH) <i>HH</i>	2	\$ 82.90	\$ 165.80
Rear Bumper Towing Cover <i>HH</i>	1	\$ 98.80	\$ 98.80
Rear Bumper Reserve Light (Parking Brake Light) <i>Socket</i>	1	\$ 328.60	\$ 328.60
Licence Lamp <i>mounting broken</i> <i>broken</i>	1	\$ 193.53	\$ 193.53
Tail Lamp(LH/RH) <i>mounting broken</i>	2	\$ 935.40	\$ 1,870.80
Tail Lamp Quarter Panel(LH/RH) <i>HH</i>	2	\$ 208.90	\$ 417.80
Rear Panel <i>Panel</i>	1	\$ 532.00	\$ 532.00
Antenna Assy - TRUNK <i>mounting broken</i>	1	\$ 689.50	\$ 689.50
Rear Panel Garnish <i>defunct</i>	1	\$ 346.80	\$ 346.80
Spare Tyre Holder <i>HH</i>	1	\$ 223.10	\$ 223.10
Spare Wheel Lock Nut <i>HH</i>	1	\$ 89.50	\$ 89.50
Spare Tyre Panel <i>HH</i>	1	\$ 892.50	\$ 892.50
Spare Tyre Panel Cushion <i>HH</i>	1	\$ 692.50	\$ 692.50
Rear tray tools box RH <i>Kit</i>	1	\$ 675.30	\$ 675.30
Rear tray tools box LH <i>see kit</i>	1	\$ 693.20	\$ 693.20
REAR TRAY LUGGS CENTER <i>defunct</i>	1	\$ 354.20	\$ 354.20
Assy BSD Blind Spot Radar (LH/RH) <i>O/S bracket kit</i> <i>W/S HH</i>	2	\$ 1,784.40	\$ 3,568.80
SUB TOTAL			\$ 22,804.63
LESS 20%			\$ 4,560.93
DISCOUNTED TOTAL			\$ 18,243.70
Reverse camera ASSY <i>HH</i> SN	1	\$ 983.20	\$983.20
Boot Lid City Cab Logo & Tel No Sticker <i>Hee</i> SN	1	\$ 35.00	\$ 35.00
Boot Lid Advertisement Logo <i>Hee</i> SN	1	\$ 100.00	\$ 100.00
Rear No.Plates + Trim Cover <i>Kit destroyed</i> SN	1	\$ 45.00	\$ 45.00
Rear Windscreen Sealant <i>Hee</i> SN	2	\$ 46.00	\$ 92.00
Rear Bumper Advertisement Logo <i>Hee</i> SN	1	\$ 50.00	\$ 50.00
Rear Bumper Rubber Mat <i>defunct</i> SN	1	\$ 50.00	\$ 50.00
Rear Bumper Reverse Sensor <i>Panel</i> SN	1	\$ 180.00	\$ 180.00
SPARE TYRE PANEL TOP COVER SILICON <i>HH</i> SN	1	\$ 250.00	\$ 250.00

X

✓

✓

X

X

X

✓

✓

✓

X

✓

✓ 40.50

✓

X

X

X

X

✓

✓

✓

✓

15,249.53

12,199.62

X

✓

✓

✓

✓

✓

✓

✓

X

