



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: TEO KITTY		Ref: CS/ASM22012593/Kwp3m4 Date: 02/02/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 3855E	Veh. Inspected	SLH 8184R
Policy No.	VFX/P2419138	Coverage (\$)	0.00
Claim No.	S2M04GJ8	Excess (\$)	0.00
Assign From	TEO KITTY	Assign Date	15/12/2022
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI ELANTRA (A)	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KMHD841CMHU308662	Colour	METALLIC SILVER
Odometer	88401 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	8 mm
L/H Front Tyre	195/65 R15	FALKEN	8 mm
R/H Rear Tyre	195/65 R15	FALKEN	8 mm
L/H Rear Tyre	195/65 R15	FALKEN	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	13/12/2022	Inspection Date	16/12/2022
Survey held at	60 JALAN LAM HUAT #04-53 SINGAPORE 737869		
Repairer	WIN AUTOMOTIVE SERVICES		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	