

Vehicle no. : SLH 8184R
Model : Hyundai Elantra S

Estimate - Spare Part(s)

AMH08910

Not Authorized
L1 Rep @ 49.50%
Resurvey After Paint

S/N	Qty	Descriptions	Amount
-----	-----	--------------	--------

LIST ITEMS:-

- 1 1 pc Rear bumper 495.40
- 2 1 pc Rear bumper reinforcement 329.60
- 3 1 pc Rear bumper sponge
- 4 1 pc Rear bumper rh protector
- 1 pc rear bumper lower diffuser garnish
- 2 pcs rear bumper side retainer LH & RH
- 2 pcs rear Bumper reflector LH & RH
- 1 pc bootlid
- 5 2 pcs Bootlid lamp assy LH & RH
- 2 pcs bootlid hinge LH & RH
- 1 pc bootlid weatherstrip 265.40
- 1 pc bootlid inner trim board
- 1 pc bootlid elantra emblem
- 1 pc bootlid S logo emblem
- 1 pc bootlid hyundai logo emblem
- 6 1 pc bootlid inner lock 166.70
- 7 2 pcs tail lamp LH & RH
- 8 1 pc rear end panel
- 1 pc end panel top garnish
- 1 pc End panel top garnish clips
- 2 pcs rear fender inner trim board LH & RH
- 2 set rear fender inner trim board fasteners LH & RH
- 2 pcs rear car plate lamp LH & RH
- 1 pc spare tyre panel
- 1 pc spare tyre panel board assy
- 1 pc rear exhaust muffler

\$ R 620.00 ✓
\$ R 450.00 ✓
\$ CM 125.00 ✓
\$ R 32.00 X
\$ R 320.00 ✓
\$ D11 130.00 ✓
\$ D11 160.00 ✓
\$ R 1,180.00 ✓
\$ R 880.00 ✓
\$ R 320.00 X
\$ D11 325.00 508.00
\$ R 330.00 X
\$ R 75.00 ✓
\$ R 65.00 ✓
\$ R 85.00 ✓
\$ R 285.00 ✓
\$ W 1,100.00 ✓
\$ R 450.00 ✓
\$ R 155.00 ✓
\$ R 38.00 ✓
\$ R 550.00 X
\$ R 58.00 X
\$ R 125.00 X
\$ R 780.00 X
\$ R 310.00 X
\$ R 580.00 X

\$ 9,528.00

\$ 1,905.60

Less 20%

\$ 7,622.40

Special nett item

Reverse sensor
end panel sealant
spare tyre panel sealant
rear insulator pad
rear car plate with housing
reverse camera

\$ Short 200.00 ✓
\$ R 60.00 30.00
\$ R 60.00 X
\$ R 120.00 X
\$ R 50.00 X
\$ R 250.00 X

Total parts

\$ 740.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and

Estimate - Labour			
S/N	Qty	Descriptions	Amount

LABOUR & OTHER CHARGES:-

1		To panel beat and renewal of all necessary damaged body parts	\$ 800.00	600/
2		To check wiring and rewire	\$ 60.00	20/
3		To remove & refix reverse sensor	\$ 80.00	50/
4		To remove & refix exhaust muffler	\$ ~ 80.00	X
5		To anti-rust	\$ 100.00	60/
6		to reinstall reverse camera	\$ 80.00	40/
7		to remove and reinstall bootlid components	\$ 80.00	50/
8		to remove and reinstall bootlid upholstery	\$ 80.00	60/
9		to realign rear chassis member	\$ ~ 250.00	X
10		To putty and spray-paint of affected areas	\$ 1,000.00	600/
			\$ 2,610.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey damaged parts during survey
- To display damaged parts during survey
- To resurvey damaged parts during survey
- To display damaged parts during survey
- To resurvey damaged parts during survey
- To display damaged parts during survey
- To resurvey damaged parts during survey
- To display damaged parts during survey
- To resurvey damaged parts during survey
- To display damaged parts during survey