



南方摩哆

Southern Motor

Business Reg. No: 234147/00L

Block 1006, Bukit Merah Lane 2. #01-10, Singapore 159762

Tel: 6273-0369 (3 Lines) Fax: 6274-6614

14 December 2022

EQ Insurance Company Ltd
5 Maxwell Road #17-00 Tower Block
MND Complex
SINGAPORE (069110)

Dear Sirs,

RE: Cost of repair to Yamaha YZF-R3 - FBL9424P

1pc of HeadLamp Comp	S\$	550.00
1pc of Meter Comp		785.00
1pc of HeadLamp Bracket		160.00
1pc of Meter Bracket		90.00
1pc of Body Set		850.00
1pc of Front Mudguard		65.00
1pc of Front Pole Light		185.00
1pc of Handle Bar Set		280.00
1pc of Front Fork		880.00
1pc of Steering Cone Stand		350.00
1pc of Front Sport Rim		380.00
1pc of Front Brake Disk		280.00
1pc of Front Top Brake Pump		250.00
1pc of Body Slider		140.00
1pc of Brake Pedal		65.00
1pc of Front Footrest		45.00
1pc of Footrest Bracket		140.00
1pc of Exhaust Pipe		860.00
1pc of Clutch Cover		280.00
1pc of Mirror		180.00
1pc of Brake Lever		35.00
1pc of Clutch Lever		35.00
1pc of Handle Switch LH		135.00
1pc of Radiator		430.00
1pc of Steering Cone		120.00
1pc of Handle Bar Bracket		180.00

7,750.00

Less 10% 775.00

Nett 6,975.00

Transport 40.00

Gasket 20.00

Engine Oil 60.00

Jack Body & Alignment 450.00

IU 165.00

Labuor 650.00

\$8,360.00



Yours Faithfully,
Southern Motor

Date: 14 December 2022

Southern Motor
Blk 1006 Bukit Merah Lane 2
#01-10
Singapore 159762

Motor Claims Department
EQ Insurance Company Ltd
5 Maxwell Road #17-00 Tower Block
MND Complex
Singapore 069110

Dear Sirs,

RE: ACCIDENT INVOLVING FBL9424P AND SLL6496H ALONG
Farrer Road at Woollerton Park Junction ON 29-10-2022 AT 18:25 PM

Please be informed that the above-said motorcycle bearing registration no: FBL9424P was seriously damaged during the above-said accident and was beyond economic repair.

Kindly arrange for your surveyor to survey the above-mentioned motorcycle at Blk 1006, Bukit Merah Lane 2 #01-10 Singapore 159762. (Tel:62730369)

Thanking you in advance,

Yours Faithfully,


Enc.