

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22012596/SVP3M4**Date:** 31/01/2023**REFERENCE****Insured/Claimant:** NG BOON HWA **Policy No:** DMPCSNW00049612201**Date of Loss:** 08/12/2022 **Nature of Claim:** OD **Claim No:** SNM22D208851/C01/CHNGPW**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: SMW2339K
Make & Model: TOYOTA CAMRY, 2.0 (A) **Engine No:** 1AZE206375
Reg. Date: 01/03/2011 (Man. Year: 2011) **Chassis No:** MR053BK4107072380
Colour: Silver **Odometer:** 0 km
Engine Capacity: 1998 cc
Market Value/New Car Price: S\$72,000.00
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: **Steering (Serviceable):** Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 215/60R16 **Rear Tyre Size:** 215/60R16
Front Left Side: Dunlop 5 mm **Rear Left Side:** Dunlop 5 mm
Front Right Side: Dunlop 5 mm **Rear Right Side:** Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,890.00	0.00	14,890.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,829.48	0.00	2,829.48	100.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	17,719.48	0.00	17,719.48	100.00
- Excess (\$\$)	0.00	600.00	-600.00	
(\$\$)	17,719.48	-600.00	18,319.48	103.39
+ GST 7.00/0.00% (\$\$)	1,240.36	0.00	1,240.36	100.00
Nett Amount (\$\$)	18,959.84	-600.00	19,559.84	103.16

INSPECTION

Date of Assignment: 16/12/2022 **Present Location:** Jin Auto Services Pte Ltd (Defu)
Date Inspected: 16/12/2022 **Inspected At:** Jin Auto Services Pte Ltd (Defu)
Blk 14 Defu Lane 10, #01-410/412
Singapore 539195
Estimated Period of Repair: 0.0 days

Adjuster: S Mohamed Irfan Bin Mohamed Iqbal**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$72,000.00
OMV :	\$23,514.00
PARF Rebate (1) :	\$0
Quota Premium Paid :	\$40,714.00
COE Rebate (2) :	\$32,691.00
Total Rebate (1) + (2) = :	\$32,691.00

The total amount incurred will be Market Value \$72,000.00 minus Total Rebate \$32,691.00 = \$39,309.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Jan 2023)
Parts:	143	TOYOTA CAMRY 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMW2339K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*IU		15.00 F	*- F
2	1		*00 Total Parts 14,875.00		14,875.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					14,890.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOTAL LABOUR	New	1,604.40	0.00
2	Total Paint Including Material	New	1,225.08	0.00
Gross Labour Cost (S\$)			2,829.48	0.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >