

Your Ref : SNM22D208851/C01

Date: 31st January 2023

Our Ref : CS/CTI22012596/Svp3m4

M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SMW 2339K
ACCIDENT ON 08/12/2022**

Instruction was received to inspect the vehicle Reg. No. SMW 2339K. The inspection was conducted on 16/12/2022 at the premises of M/s Jin Auto Services Pte Ltd, Blk 14 Defu Lane 10, #01-410/412, Singapore 539195.

The following vehicle information was recorded:

Registration Number	: SMW 2339K
Make/Model	: Toyota Camry 2.0 Auto Abs Airbag
Year of Registration	: 2011
Body Colour	: Silver
Chassis Number	: MR053BK4107072380
Engine Capacity	: 1998 cc

The vehicle sustained damages at the front portion. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 72,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 32,691.00)
Nett Liability	<u>S\$ 39,309.00</u> =====

Vehicle Inspected By:



S MOHAMED IRFAN BIN MOHAMED IQUBAL
Asst. Automotive Assessor



K.K.LAU
MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.