

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Adeline Chng Pei Wen

Date: 21 Dec 2022

Preliminary Advice

Vehicle No	: SMW2339K	Accident Date	: 08/12/2022
Make	: TOYOTA CAMRY	Policy No.	: DMPCSNW00049612201
Assignment Date	: 16/12/2022	Excess	: S\$100.00
Date of Inspection	: 16/12/2022	Est. Duration of Repair	: 0
Inspection At	: JIN AUTO SERVICES PTE LTD (DEFU) BLK 14 DEFU LANE 10, #01-410/412 SINGAPORE 539195		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	-
Revised Amount	:S\$	-
Check Items (Estimated)	:S\$	-
Total	:S\$	-
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	72,000.00
COE / PARF Rebate	:S\$	32,691.00
Salvage Value	:S\$	
Margin for Repair	:S\$	39,309.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please be informed that engine and gearbox damaged.