

**Thiam Heng Huat Pte Ltd**

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721  
 Mobile: (65) 8263 6295 Email: thiamhenghuat@gmail.com

Make/Model: MERCEDES BENZ C180 ESTATE

Engine/Chassis No.: WDB2032462F942879


Date of accident:

Damaged area: O/S Front, N/S &amp; Rear

Date: 16/12/2022

Claim Type: TP

VRN: SKG138U



| List items |                                   |                |     |             |             |
|------------|-----------------------------------|----------------|-----|-------------|-------------|
| S/N        | Parts description                 |                | QTY | UNIT PRICE  | AMOUNT      |
| 1          | Tailgate                          | R              | 1   | \$ 1,873.00 | \$ 1,873.00 |
| 2          | Tailgate lock                     | nd             | 1   | \$ 313.00   | \$ 313.00   |
| 3          | Tailgate lock striker             | R              | 1   | \$ 67.00    | \$ 67.00    |
| 4          | Tailgate licence plate lamp       | R              | 2   | \$ 129.00   | \$ 258.00   |
| 5          | Tailgate outer garnish            | Warp           | 1   | \$ 335.00   | \$ 335.00   |
| 6          | Tailgate inner trim               | R              | 1   | \$ 467.00   | \$ 467.00   |
| 7          | Tailgate 'C180' emblem            | nd             | 1   | \$ 44.00    | \$ 44.00    |
| 8          | Tailgate 'KOMPRESSOR' emblem      | nd             | 1   | \$ 69.00    | \$ 69.00    |
| 9          | Tailgate 'MERCEDES BENZ' logo     | nd             | 1   | \$ 76.00    | \$ 76.00    |
| 10         | Rear bumper center moulding       | nd             | 1   | \$ 286.00   | \$ 286.00   |
| 11         | Rear bumper inner carrier         | 271 CM         | 1   | \$ 337.00   | \$ 337.00   |
| 12         | Rear bumper                       | R              | 1   | \$ 1,195.00 | \$ 1,195.00 |
| 13         | Rear bumper side retainer         | R              | 2   | \$ 55.00    | \$ 110.00   |
| 14         | Rear bumper reinforcement         | R              | 1   | \$ 459.00   | \$ 459.00   |
| 15         | Rear bumper reinforcement bracket | R              | 2   | \$ 78.00    | \$ 156.00   |
| 16         | End panel                         | R              | 1   | \$ 555.00   | \$ 555.00   |
| 17         | End panel top garnish             | R              | 1   | \$ 176.00   | \$ 176.00   |
| 18         | Spare wheel compartment           | CM             | 1   | \$ 772.00   | \$ 772.00   |
| 19         | Spare wheel panel top board       | R              | 1   | \$ 194.00   | \$ 194.00   |
| 20         | Rear bumper lower cowl            | R              | 1   | \$ 263.00   | \$ 263.00   |
| 21         | Taillamp                          | 0546 R/SCM     | 2   | \$ 617.00   | \$ 1,234.00 |
| 22         | Taillamp panel                    | R              | 2   | \$ 106.00   | \$ 212.00   |
| 23         | Rear fender                       | R              | 2   | \$ 818.00   | \$ 1,636.00 |
| 24         | Rear fender inner trim            | R              | 2   | \$ 95.00    | \$ 190.00   |
| 25         | Rear fender cowl                  | R              | 2   | \$ 128.00   | \$ 256.00   |
| 26         | Tailgate weatherstrip             | DI/RA          | 1   | \$ 185.00   | \$ 185.00   |
| 27         | Tailgate hinge                    | R              | 2   | \$ 47.00    | \$ 94.00    |
| 28         | Rear windscreen moulding          | R              | 1   | \$ 155.00   | \$ 155.00   |
| 29         | Exhaust assy                      | R              | 1   | \$ 1,450.00 | \$ 1,450.00 |
| 30         | Exhaust assy holder               | R              | 2   | \$ 38.00    | \$ 76.00    |
| 31         | Exhaust assy heatshield           | R              | 1   | \$ 189.00   | \$ 189.00   |
| 32         | Front fender                      | 554 O/S R MS R | 2   | \$ 883.00   | \$ 1,766.00 |
| 33         | Front fender outer moulding       | O/S R MS R     | 2   | \$ 78.00    | \$ 156.00   |

**LKK Auto Consultants** hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

NOT Authorized

1/12/22 @ 13,900/h

Recovery After Paint

12 days

# Repair Estimate

|    |                                        |        |   |                      |                     |   |
|----|----------------------------------------|--------|---|----------------------|---------------------|---|
| 34 | Front door n/s                         | R      | 1 | \$ 1,259.00          | \$ 1,259.00         | ✓ |
| 35 | Front door outer moulding n/s          | R      | 1 | \$ 95.00             | \$ 95.00            | X |
| 36 | Front door hinge n/s                   | R      | 2 | \$ 56.00             | \$ 112.00           | X |
| 37 | Front door inner trim board n/s        | R      | 1 | \$ 449.00            | \$ 449.00           | X |
| 38 | Wing mirror n/s                        | CM     | 1 | \$ 327.00            | \$ 327.00           | ✓ |
| 39 | Wing mirror outer cover n/s            | CM     | 1 | \$ 163.00            | \$ 163.00           | ✓ |
| 40 | Wing mirror signal lamp n/s            | B      | 1 | \$ 75.00             | \$ 75.00            | ✓ |
| 41 | Rear bumper sensor holder              | R      | 4 | \$ 12.00             | \$ 48.00            | X |
| 42 | Front bumper sensor holder             | R      | 6 | \$ 12.00             | \$ 72.00            | ✓ |
| 43 | Front fender inner shield o/s          | CM     | 1 | \$ 185.00            | \$ 185.00           | ✓ |
| 44 | Front bumper 1105                      | B      | 1 | \$ 1,235.00          | \$ 1,235.00         | ✓ |
| 45 | Front bumper side carrier              | R      | 2 | \$ 78.00             | \$ 156.00           | X |
| 46 | Front bumper side moulding o/s         | R      | 1 | \$ 116.00            | \$ 116.00           | ✓ |
| 47 | Front bumper foglamp o/s 345           | mg, CM | 1 | \$ 378.00            | \$ 378.00           | ✓ |
| 48 | Front bumper foglamp inner bracket o/s | R      | 1 | \$ 53.00             | \$ 53.00            | X |
| 49 | Front bumper reinforcement o/s         | R      | 1 | \$ 553.00            | \$ 553.00           | X |
| 50 | Front bumper reinforcement bracket o/s | R      | 1 | \$ 48.00             | \$ 48.00            | X |
| 51 | Headlamp o/s                           | mg, CM | 1 | \$ 938.00            | \$ 938.00           | ✓ |
| 52 | Headlamp lower bracket o/s             | R      | 1 | \$ 29.00             | \$ 29.00            | X |
| 53 | Front shock absorber o/s               | R      | 1 | \$ 362.00            | \$ 362.00           | ✓ |
| 54 | Front shock absorber top mount o/s     | R      | 1 | \$ 71.00             | \$ 71.00            | ✓ |
| 55 | Front wheel carrier o/s                | R      | 1 | \$ 595.00            | \$ 595.00           | ✓ |
| 56 | Front wheel carrier hub o/s            | R      | 1 | \$ 245.00            | \$ 245.00           | ✓ |
| 57 | Front lower arm o/s                    | R      | 1 | \$ 347.00            | \$ 347.00           | ✓ |
| 58 | Front end link o/s                     | R      | 1 | \$ 125.00            | \$ 125.00           | X |
| 59 | Front tie rod end o/s                  | R      | 1 | \$ 95.00             | \$ 95.00            | X |
| 60 | Front inner tie rod o/s                | R      | 1 | \$ 173.00            | \$ 173.00           | X |
| 61 | Front control arm o/s 316              | R      | 1 | \$ 369.00            | \$ 369.00           | ✓ |
|    |                                        |        |   | <b>Subtotal</b>      | <b>\$ 24,277.00</b> |   |
|    |                                        |        |   | <b>List discount</b> | <b>10.00%</b>       |   |
|    |                                        |        |   | <b>Total</b>         | <b>\$ 21,849.30</b> |   |

## Special nett items

| No. | Parts description                     | QTY | UNIT PRICE | AMOUNT    |      |
|-----|---------------------------------------|-----|------------|-----------|------|
| 1   | Front & Rear licence plate & frame    | 2   | \$ 55.00   | \$ 110.00 | X    |
| 2   | Reverse sensor                        | 42  | \$ 180.00  | \$ 720.00 | ✓    |
| 3   | Tailgate outer garnish clips          | 8   | \$ 5.50    | \$ 44.00  | ✓    |
| 4   | Tailgate inner trim clips             | 10  | \$ 5.50    | \$ 55.00  | ✓    |
| 5   | Rear bumper clips                     | 12  | \$ 5.50    | \$ 66.00  | ✓    |
| 6   | End panel sealant                     | 1   | \$ 80.00   | \$ 80.00  | 305m |
| 7   | End panel top garnish clips           | 6   | \$ 5.50    | \$ 33.00  | ✓    |
| 8   | Spare wheel compartment sealant       | 1   | \$ 80.00   | \$ 80.00  | 405m |
| 9   | Taillamp panel sealant                | 2   | \$ 30.00   | \$ 60.00  | X    |
| 10  | Rear fender inner trim clips          | 12  | \$ 5.50    | \$ 66.00  | X    |
| 11  | Rear fender cowlings clips            | 12  | \$ 5.50    | \$ 66.00  | X    |
| 12  | Rear windscreen sealant               | 1   | \$ 80.00   | \$ 80.00  | 405m |
| 13  | Front door inner trim board clips n/s | 10  | \$ 5.50    | \$ 55.00  | X    |
| 14  | Front fender inner shield clips o/s   | 8   | \$ 5.50    | \$ 44.00  | ✓    |
| 15  | Front bumper clips                    | 12  | \$ 5.50    | \$ 66.00  | ✓    |

LKK Auto Consultants (Pty) Ltd.  
 the Repair of the following:  
 • To remove damaged parts and replace  
 • To replace damaged parts and repair  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modifications are allowed  
 • Supplemental items must be reviewed and  
 is subject to final approval from Insurance Company  
 Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_

Repair Estimate

|    |                       |        |              |                    |   |
|----|-----------------------|--------|--------------|--------------------|---|
| 16 | Front bumper sensor   | 9001 1 | \$ 180.00    | \$ 1,080.00        | ✓ |
| 17 | Front alloy wheel o/s | 9001 1 | \$ 550.00    | \$ 550.00          |   |
| 18 | Front tyre o/s        | Per 1  | \$ 280.00    | \$ 280.00          |   |
| 19 | Sundries              | nn 1   | \$ 50.00     | \$ 50.00           | X |
|    |                       |        | <b>Total</b> | <b>\$ 3,585.00</b> |   |

| Labour              |                                                                                                                                    |           |                    |       |
|---------------------|------------------------------------------------------------------------------------------------------------------------------------|-----------|--------------------|-------|
| No.                 | Description                                                                                                                        | Work unit | Amount             |       |
| 1                   | To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts. | 10        | \$ 2,000.00        | 1200L |
| 2                   | To disconnect wire harnesses of electrical components to facilitate repairs, reconnect and check functions.                        | 0.5       | \$ 100.00          | 600   |
| 3                   | To remove, refit tailgate components and replace tailgate, check and re-adjust close gap, alignment and water seepage.             | 0.5       | \$ 100.00          | 600   |
| 4                   | To remove and refit o/s front tyre & rim for replacement. To perform tyre balancing.                                               | 0.25      | \$ 50.00           | X     |
| 5                   | To remove and refit rear windscreen to facilitate repair work.                                                                     | 0.75      | \$ 150.00          | 1200  |
| 6                   | Supply spray paint material and necessary items to respray affected area / panel.                                                  | 9         | \$ 1,800.00        | 14000 |
| 7                   | To rust proof all affected portions after repair.                                                                                  | 0.5       | \$ 100.00          | 900   |
| 8                   | To remove and refit n/s front door components to replace n/s front door, check alignment.                                          | 0.5       | \$ 100.00          | 600   |
| 9                   | To remove and refit o/s front undercarriage for replacement of parts.                                                              | 1         | \$ 200.00          | ✓     |
| 10                  | To conduct computerized wheel alignment.                                                                                           | 0.5       | \$ 100.00          | 600   |
| <b>Total labour</b> |                                                                                                                                    |           | <b>\$ 4,700.00</b> |       |

|                             |                     |
|-----------------------------|---------------------|
| <b>Estimate Grand Total</b> | <b>\$ 30,134.30</b> |
|-----------------------------|---------------------|