



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SMD9959A

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information

WIP No **61385**
Reg No/Reg Date **SMD9959A / 20/03/2019**
Date In/Mileage **30/01/2023/ 67314**
Chassis No **WDD1173422N7473649**
Engine No **27091031811995**
Make/Model **MB/MB CLA 180**
Colour/Trim **028 890 Cavansite B/ 041 151 ARTICO Spor**

Account No	Terms	Date/Time Printed	CSE	Operator				
WC000668	Credit	01/02/2023/ 15:42	K0	301 / Kerlyn Ong				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
Z REQUEST								
Customer Request								
M BPNSUN								
POLICY NO/ACC DATE : DMPCSNW00126462200 // 30/11/2022								
DRIVE IN/EXCESS : 30/11/2022 // SNE9994E - CHINA								
DATE IN/DATE SURVEY: 30/01/2023 1115 // LKK - RASUL								
DIRECT SETTLEMENT : 03/01/2023 // CHINA - JACQUELINE								
A BPILAB								960.00
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.							0.05	800.00
A BPIRES								
RESPRAY REAR BUMPER							0.10	380.00
A BPILAB								
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT								120.00
A BPILAB								
CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT					1.00	1252.41	00.00	1252.41
X REAR BUMPER					1.00	358.12	00.00	358.12
X REAR BUMPER LOWER TRIM					1.00	209.53	00.00	209.53
X CTR/ REAR BUMPER MOULDING								

Finalization

Confirmed & accepted by

Nett **4,080.06**
8% GST on **4080.06** **326.40**
Total Payable 4,406.46

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG