

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

TP Budget Direct.
Xin Yu.

TAN SIEW GIM

BLK 332 HOUGANG AVE 5 #09-216

SINGAPORE 530332

TAX INVOICE

Repair Code : CLM15760

Date in : 16/12/2022

Vehicle Num. : CB6433Z

Model : TOYOTA COASTER 19 SEATER

Chassis/Eng# : JTGFC538303000365/N04CTQ12768

Contact : 92973052

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
ENGINE INTERCOOLER <i>Dented</i>	1	2851.50	✓ 2,851.50
FRONT BRACE PANEL <i>Bent</i>	1	160.60	✓ 160.60
FRONT BUMPER <i>Distorted</i>	1	1468.60	1258 ✓ 1,468.60
FRONT BUMPER BRACKET L/R <i>Bent</i>	2	61.60	✓ 123.20
FRONT BUMPER REINFORCEMENT <i>Dented</i>	1	1370.50	895 ✓ 1,370.50
FRONT BUMPER RH FOGLAMP <i>Crushed</i>	1	310.40	✓ 310.40
FRONT BUMPER RH FOGLAMP BRACKET <i>Crushed</i>	1	100.70	✓ 100.70
FRONT BUMPER RH FOGLAMP COVER <i>Crushed</i>	1	142.10	✓ 142.10
FRONT GRILLE <i>Crushed</i>	1	845.00	396 ✓ 845.00
FRONT HEADLAMP L/R <i>Crushed</i>	2	845.40	✓ 1,690.80
FRONT HEADLAMP PANEL <i>Repair</i>	1	191.00	✓ 191.00
FRONT LOWER UNDER PANEL COVER <i>see one</i>	1	252.00	1026390 ✓ 252.00
FRONT PANEL 'LOGO' EMBLEM <i>New</i>	1	80.10	✓ 80.10
FRONT PANEL (INNER) <i>Repair</i>	1	988.10	769792 ✓ 988.10
FRONT PANEL (OUTER) <i>Dented</i>	1	2006.20	✓ 2,006.20
FRONT WINDSCREEN GLASS WEATHER STRIP <i>New</i>	1	391.40	✓ 391.40

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TAN SIEW GIM
BLK 332 HOUGANG AVE 5 #09-216
SINGAPORE 530332

Contact : 92973052

TAX INVOICE

Repair Code : CLM15760

Date in : 16/12/2022

Vehicle Num. : CB6433Z

Model : TOYOTA COASTER 19 SEATER

Chassis/Eng# : JTGFC538303000365/N04CTQ12768

	Subtotal before discount	12,972.20
Percentage discount 25%		3,243.05
	Sub-total 1	9,729.15
FRONT GRILLE CLIPS - SET <i>Hee</i>	1	50.00 <i>30</i> 50.00
FRONT NUMBER PLATE <i>Hee</i>	1	35.00 <i>+</i> 35.00
FRONT PANEL SEALANT <i>Hee</i>	1	80.00 <i>60</i> 80.00
	Subtotal before discount	165.00
Percentage discount 0%		0.00
	Sub-total 2	165.00
	Parts-total	9,894.15

LABOUR

To remove, reinstall electrical wiring harness, check lighting. (to FR)

To remove, reinstall windscreen. (to FR)

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To remove, reinstall dashboard fascia, meter reading and etc. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

1860

Labour Total	4,190.00
Parts & Labour Total	14,084.15

*** This is a computer-generated document which requires no signature.***

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

page 2

Adrian Lim
h/s 21/12/22

07 Days
total: 974792
h/s: 7.8k