



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22012610/Awy3m4 Date: 29/03/2023	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMP 4113T	Veh. Inspected	CB 6433Z	
Policy No.	P10802920R00	Coverage (\$)	0.00	
Claim No.	C10018305/KY	Excess (\$)	0.00	
Assign From	MAYBIE CHUA	Assign Date	16/12/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA COASTER	c.c	4009	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	JTGFC538303000365	Colour	SILVER	
Odometer	347889 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	7.00 R16	GT RADIAL	6 mm	
L/H Front Tyre	7.00 R16	GT RADIAL	6 mm	
R/H Rear Tyre	7.00 R16	GT RADIAL	6 mm	
L/H Rear Tyre	7.00 R16	GT RADIAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/10/2022	Inspection Date	19/12/2022	
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	