ASS, REC. BY:	
AS	SIGNMENT
From: Date:	Veh No: 8mw88564 Yr Regn: 2020, Oct.
Estimated Cost:	Type: M.Car/ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
DD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Hyudai Avante c.c 1598
at Workshop m/s	Colour A/C: Insured / Std / NI / NA
of	Sp.Reading 24141 T/Radio: Insured / Std / NI / NA
nsured:	Eng/No:
Policy No.	C/No: KMrILN41ETMU066619
Claims No.	Gen. Cond. Good) Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
	Tyre Size: F: 2 > 5 / 5 S R 1 6 -
(Policy Condition)	R: 205/55R16
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or tankook.
Bal. or Market Value:	Front Rear
DAC Accident Rport: Consistent? : Yes or No	R/Bal. 86 mm R/Bal. 86 mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 06 mm L/Bal. 06 mm
Est. Repairs: days Res.: Yes or No	D.O.A. D.O.I. 29 11/22
um Sum: % 3 Val.: Yes or No	Survey held at TK Lee
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / Q/S / N/S / U/C / Rooftop or
Vehicle: IN / OU	Tront 0/s,
Date:Person Contacted:	The U/C / Chassis frame Body Structure affected due to collision
Date / Time Action / Instruction TP Chron	£ :
11 Ct Vieta	
MV:	
PV:	
Nett:	
·	633c
ate/Time, File Pass to? : Preli. Report	Days Of Repair:
: Final Report	Resurvey No. of Trip: Survey Fee:
eate/Time, File Return to?	Transportation:
Add F	ee: :Site Insp (\$)_s+Rs_s
	: Interview (\$) Photos
teport Former:	