

YSK AUTO

1 KAKI BUKIT AVENUE 6
#01-71 AUTOBAY SINGAPORE 417883

VEHICLE DETAILS

VEHICLE NO : SMY2540J
VEHICLE MODEL : TOYOTA RAIZE
CHASSIS NO : A200AE0038111

TP A16.

Xiao Tony

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL	
1	REAR NUMBER PLATE LAMP <i>Not new</i>	2	\$ 65.00	\$ 130.00	+
2	REAR BUMPER <i>Distorted</i>	1	\$ 1,245.00	\$ 1,245.00	-
3	REAR BUMPER SIDE HOLDER <i>new</i>	2	\$ 84.00	\$ 168.00	+
4	REAR BUMPER REFLECTOR <i>Not new</i>	2	\$ 95.00	\$ 190.00	+
5	REAR BUMPER LOWER SPOILER <i>Del'd</i>	1	\$ 652.00	\$ 652.00	-
6	REAR BUMPER SIDE GRILLE <i>Not new</i>	2	\$ 131.00	\$ 262.00	+
7	REAR END PANEL <i>Del'd</i>	1	\$ 721.00	\$ 721.00	-
8	REAR END PANEL TOP GARNISH <i>Del'd</i>	1	\$ 235.00	\$ 235.00	-
9	REAR END PANEL ANTENNA SENSOR <i>Del'd</i>	1	\$ 198.00	\$ 198.00	-
10	REAR END PANEL AIR VENT <i>Del'd</i>	2	\$ 42.00	\$ 84.00	-
11	TAILLAMP <i>Cracked</i>	2	\$ 475.00	\$ 950.00	-
12	TAILGATE <i>Distorted</i>	1	\$ 1,580.00	\$ 1,580.00	-
13	TAILGATE LOCK <i>Del'd</i>	1	\$ 393.00	\$ 393.00	-
14	TAILGATE WEATHERSTRIPE <i>Del'd</i>	1	\$ 355.00	\$ 355.00	-
15	TAILGATE GLASS MOULDING <i>new</i>	1	\$ 121.00	\$ 121.00	-
16	REAR FENDER INNER TRIM BOARD <i>Del'd</i>	2	\$ 545.00	\$ 1,090.00	+
17	REAR FENDER ARC GARNISH <i>RT Del'd</i>	2	\$ 206.00	\$ 412.00	206.
18	SPARE TYRE PANEL <i>new</i>	1	\$ 1,249.00	\$ 1,249.00	+
19	SPARE TYRE PANEL TOP BOARD <i>Del'd</i>	1	\$ 525.00	\$ 525.00	-
20	REAR EXHAUST PIPE <i>2 All</i>	1	\$ 615.00	\$ 615.00	+
21	REAR EXHAUST PIPE MOUNTING <i>new</i>	1	\$ 36.00	\$ 36.00	+
22	REAR EXHAUST PIPE GASKET <i>new</i>	2	\$ 31.00	\$ 31.00	+

TOTAL PRICE: \$ 11,242.00
LESS 25% \$ 2,810.50
SUB TOTAL PRICE: \$ **8431.50**

8355
6266.25

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL	
1	REAR NUMBER PLATE <i>Del'd</i>	1	\$ 30.00	\$ 30.00	✓
2	REAR NUMBER PLATE HOLDER <i>Del'd</i>	1	\$ 30.00	\$ 30.00	✓
3	REAR BUMPER CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00	✓
4	REAR BUMPER LOWER SPOILER GARNISH <i>Del'd</i>	1	\$ 800.00	\$ 800.00	500.
5	REVERSE SENSOR <i>Del'd</i>	1 SET	\$ 280.00	\$ 280.00	280
6	REAR END PANEL TOP GARNISH CLIPS <i>new</i>	1 SET	\$ 20.00	\$ 20.00	✓
7	REAR END PANEL SEALANT <i>new</i>	1 SET	\$ 60.00	\$ 60.00	✓
8	TAILGATE GLASS SEALANT <i>new</i>	1 SET	\$ 60.00	\$ 60.00	✓
9	REAR FENDER INNER TRIM CLIPS <i>Not new</i>	2 SETS	\$ 30.00	\$ 60.00	+
10	REAR FENDER ARC GARNISH CLIPS <i>new</i>	2 SETS	\$ 20.00	\$ 40.00	20.

11	SPARE TYRE PANEL INSULATION PADS <i>NEW</i>	1 SET	\$ 280.00	\$ 280.00	<i>✓</i>
12	REAR EXHAUST PIPE COVER (AKRAPOVIC) <i>NEW</i>	1	\$ 200.00	\$ 200.00	<i>✓</i>
			TOTAL :	\$ 1,890.00	

950

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,600.00	<i>1100</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,400.00	<i>900</i>	
3	WIRING CHECK	\$ 100.00	<i>30</i>	
4	TO APPLY TUFF COAT	\$ 150.00	<i>100</i>	
5	TO REMOVE REVERSE SENSOR	\$ 100.00	<i>50</i>	
6	TO REMOVE REAR CAMERA	\$ 100.00	<i>50</i>	
7	TO REMOVE VIDEO RECORDER	\$ 100.00	<i>50</i>	
8	TO REMOVE UPHOLSTERY & REAR SEAT	\$ 300.00	<i>80</i>	
9	TO TRANSFER TAILGATE FITTINGS	\$ 150.00	<i>80</i>	
10	TO REMOVE TAILGATE GLASS	\$ 180.00	<i>120</i>	
11	TO REMOVE EXHAUST PIPE	\$ 150.00	<i>X</i>	

TOTAL: \$ 4,330.00

2560

ESTIMATE REPORT

TOTAL PARTS COST: \$ 10321.50

TOTAL LABOUR COST: \$ 4330

TOTAL REPAIR COST: \$ 14651.50

Total: 9776.25

H/S : 7.8K. ✓

APPROVED DETAILS

SURVEYOR:

CONTACT:

FAX:

PART BY PART / LUMP SUM:

NO. OF DAYS:

07 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: