



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Ref: CS3/LPC22008577/Dvy3e2-1

Date: 16/01/2023

Code: LPC2

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	YQ 222R	<b>Veh. Inspected</b>	YQ 4760C
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	22/22/22/VC05/026212	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	ENG HUEY NI	<b>Assign Date</b>	18/12/2022

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	mitsubishi fuso FM65FM6RDEA	<b>c.c</b>	7545
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2021
<b>Chassis No.</b>	FM65FMA40103	<b>Colour</b>	WHITE
<b>Odometer</b>	-	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	11 R22.5	DUNLOP	6 mm
<b>L/H Front Tyre</b>	11 R22.5	DUNLOP	6 mm
<b>R/H Rear Tyre</b>	11 R22.5 (D)	DUNLOP	6/6 mm
<b>L/H Rear Tyre</b>	11 R22.5 (D)	DUNLOP	6/6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	25/08/2022	<b>Inspection Date</b>	05/09/2022
<b>Survey held at</b>	DERRICK MOTOR WORKS BLK 9002 #01-72 TAMPINES ST 93 SINGAPORE 528836		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>7 Working Days</b>
-------------------------------------	-----------------------