

TP liberty.
Ani Rong

RN61084884

JDM AUTOCARE

BLK 1 KAKI BUKIT AVENUE 6, #01-51, AutoBay@Kaki Bukit Singapore 417883
UEN NO : 53060650W

DATE : 08/12/2022

VEHICLE NO : SLN761X HONDA STREAM

ITEMS	QTY	Amount
1 RH FRONT DOOR <i>new</i>	1	\$1,486.60 <i>+</i>
2 RH REAR DOOR <i>Defect</i>	1	\$1,652.10 <i>120</i>
3 RH REAR DOOR HINGE @\$189.20 <i>new</i>	2	\$378.40 <i>+</i>
4 RH REAR DOOR CHECKER <i>new</i>	1	\$148.10 <i>+</i>
5 RH REAR DOOR WEATHER STRIPE <i>new</i>	1	\$198.50 <i>+</i>
6 RH REAR DOOR INNER TRIM BOARD <i>Defect</i>	1	\$498.20 <i>✓</i>
7 REAR DOOR INNER LOCK <i>new</i>	1	\$315.60 <i>+</i>
8 RH REAR DOOR GLASS <i>Not a</i>	1	\$162.50 <i>+</i>
9 RH REAR DOOR GLASS OUTER MOULDING <i>new</i>	1	\$162.40 <i>+</i>
10 RH REAR DOOR STICKER @\$116.20 <i>new</i>	2	\$232.40 <i>80</i>
11 RH REAR DOOR POWER WINDOW MOTOR <i>new</i>	1	\$698.40 <i>+</i>
12 RH REAR DOOR POWER WINDOW REGULATOR GEAR <i>Defect</i>	1	\$399.20 <i>295</i>
13 RH REAR FENDER <i>Defect</i>	1	\$928.70 <i>✓</i>
14 RH REAR FENDER GLASS WITH MOULDING <i>new</i> <i>nec</i>	1	\$746.80 <i>75</i>
15 RH ROCKER PANEL <i>new</i>	1	\$984.60 <i>+</i>
16 RH REAR AXLE BEAM <i>new</i>	1	\$845.10 <i>+</i>
17 RH REAR SHOCK ABSORBER <i>Defect</i>	1	\$451.50 <i>298</i>
18 RH REAR WHEEL BEARING WITH HUP <i>Defect</i>	1	\$494.70 <i>332</i>
		\$10,783.80
	DISCOUNT 20%	\$2,156.76
	TOTAL	\$8,627.04

SPECIAL NETT ITEM	QTY	Amount
1 RH REAR SPORT RIM <i>new</i>	1	\$850.00 <i>450</i>
2 RH REAR TYRE <i>new</i>	1	\$360.00 <i>+</i>
3 RH REAR FENDER GLASS SEALANT <i>new</i>	1	\$120.00 <i>70</i>
4 RH REAR DOOR INNER TRIM BOARD CLIPS <i>new</i>	1	\$60.00 <i>30</i>
5 RH FRONT DOOR INNER TRIM BOARD CLIPS <i>new</i>	1	\$60.00 <i>+</i>
		\$1,450.00
		\$10,077.04

Labour charges

- 1 TO REMOVE , REINSTALL ALL ELECTRICAL WIRING , LIGHTING
- 2 TO SUPPLY LABOUR ,WORKMANSHIP TO REMOVE AND REINSTALL AFFECTED AREAS
- 3 TO SPRAY PAINT AND RESPRAY ACCIDENT AFFECTED AREAS
- 4 TO APPLY TUFF COAT
- 5 TO REMOVE & REFIX RH REAR FENDER GLASS
- 6 LABOUR FOR REMOVE & RENEW RH FRONT UNDER CARRIAGE
- 7 TO CONDUCT WHEEL ALIGNMENT
- 8 LABOUR FOR REMOVE / REFIX AND TRANSFER RH BOTH DOORS FITTING

1780

~~\$80.00~~ 30
~~\$1,400.00~~ 700
~~\$1,200.00~~ 600
~~\$300.00~~ 60
~~\$150.00~~ 50
~~\$400.00~~ 180
~~\$150.00~~ 80
~~\$400.00~~ 80

\$4,080.00

\$14,157.04

Adrian L
 L/S 19/12/22

07 Days.

total: 5281.52

L/S: 4.21c.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: