

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : LIBERTY INSURANCE PTE LTD
51 CLUB STREET
#03-00 LIBERTY HOUSE
SINGAPORE 069428

TEL: 62218611 FAX: 62241047
ATTN: Motor Claim Department

Estimate No: EST2200407

Date: 15 Dec 2022

Veh Reg No: SGM6639S

Make/Model: HONDA VEZEL 1.5X
CVT ABS D/AIRBAG
2WD 5DR

Chasis No: RU11114258

Reg. Date: 30/09/2016

Your Ref No: SLS7957B

Claim Type: Third Party

Accident Date: 14/12/2022

TP Veh Reg No: SLS7957B

Estimate Repair Cost to Vehicle No :SGM6639S

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
List Price			
1	1 PC BOOT LID <i>Distal d</i>	1,168.10	<i>✓</i>
2	1 PC BOOT LID LOGO <i>new</i>	45.80	<i>+</i>
3	1 PC BOOTLID "VEZEL" EMBLEM <i>new</i>	48.40	<i>✓</i>
4	1 PC BOOT LID LAMP LH <i>new</i>	424.40	<i>+</i>
5	1 PC BOOT LID LAMP RH <i>could</i>	424.40	<i>✓</i>
6	1 PC BOOT LID LOCK <i>new</i>	187.10	<i>✓</i>
7	1 PC BOOT LID LOCK CHECKER <i>new</i>	39.40	<i>+</i>
8	1 PC BOOT LID RUBBER <i>cut</i>	171.10	<i>✓</i>
9	1 PC BOOTLID TRIM <i>Del d</i>	189.60	<i>✓</i>
10	1 PC REAR WINDSCREEN RUBBER <i>new</i>	120.00	<i>✓</i>
11	1 PC TAIL LAMP RH <i>cut</i>	563.90	<i>✓</i>
12	1 PC REAR PANEL <i>Distal d</i>	459.70	<i>✓</i>
13	1 PC REAR PANEL TRIM <i>Del d</i>	125.70	<i>✓</i>
14	1 PC REAR BUZZER SENSOR <i>could</i>	98.30	<i>✓</i>
15	1 PC REAR TOP HARDBOARD <i>Del d</i>	366.30	<i>✓</i>
16	1 PC REAR BUMPER <i>Del d</i>	829.60	<i>✓</i>
17	1 PC REAR BUMPER REFLECTOR - RH <i>could</i>	178.50	<i>✓</i>
18	1 PC REAR UNDER COVER <i>Del d</i>	263.30	<i>✓</i>
		5,703.60	
Less 20%		1,140.72	4,562.88
Special Net			
19	1 SET BOOT LID TRIM CLIPS <i>new</i>	60.00	<i>30</i>
20	1 PC REAR WINDSCREEN SEALANT <i>new</i>	60.00	<i>30</i>
21	1 PC REAR WINDSCREEN SEALANT RUBBER <i>new</i>	60.00	<i>30</i>
22	1 PC REAR NUMBER PLATE <i>new</i>	50.00	<i>+</i>
23	1 SET REAR PANEL TRIM CLIPS <i>new</i>	40.00	<i>20</i>
24	1 SET REVERSE SENSORS <i>new</i>	250.00	<i>200</i>
25	1 SET REAR BUMPER CLIPS <i>new</i>	40.00	<i>30</i>
1 set Rear under cover clips <i>new</i>		40.00	<i>30</i>

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : LIBERTY INSURANCE PTE LTD
51 CLUB STREET
#03-00 LIBERTY HOUSE
SINGAPORE 069428

TEL: 62218611 FAX: 62241047
ATTN: Motor Claim Department

Estimate No: EST2200407

Date: 15 Dec 2022

Veh Reg No: SGM6639S
Make/Model: HONDA VEZEL 1.5X
CVT ABS D/AIRBAG
2WD 5DR

Chasis No: RU11114258

Reg. Date: 30/09/2016

Your Ref No: SLS7957B

Claim Type: Third Party
Accident Date: 14/12/2022
TP Veh Reg No: SLS7957B

Estimate Repair Cost to Vehicle No :SGM6639S

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
		560.00	560.00
	Labour		
26	1 TO CHECK WIRING	50.00 30	
27	1 TO REMOVE AND REFIT REAR WINDSCREEN	120.00 ✓	
28	1 TO REMOVE AND REFIT VIDEO CAMERA	80.00 50	
29	1 TO REMOVE AND REFIT REVERSE CAMERA	80.00 50	
30	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00 50	
31	1 TO REMOVE AND REFIT INNER TRIM	100.00 80	
32	1 TO SPRAY PANEL SEALANT	80.00 180 ✓	
33	1 (REAR) TO SPRAY PAINTING	1,000.00 80	
34	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,200.00 800	
		2,790.00	2,790.00
		Total	S\$ 7,912.88
		Add GST @ 7%	553.90
		Total Amount Payable	S\$ 8,466.78

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

TOTAL: SINGAPORE DOLLAR EIGHT THOUSAND FOUR HUNDRED SIXTY SIX AND CENTS
SEVENTY EIGHT ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time
which may be required after work has begun.

ed by Repairer

5350