



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)		Ref:	CS/SPF22012637/Rny3m4
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE) POLICE LOGISTICS BASE (PLB) 1		Date:	30/01/2023
HEMMANT ROAD SINGAPORE 438675			
ATTN: HAFIZUL FARHAN		Code:	SPF
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	QX 364Y	Veh. Inspected	SMP 7992C
Policy No.		Coverage (\$)	0.00
Claim No.	ACS/105/009/2022/111	Excess (\$)	0.00
Assign From	HAFIZUL FARHAN	Assign Date	19/12/2022
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI OS KONA EV	c.c	0
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	KMHK281GUKU039219	Colour	GREY
Odometer	231567 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/55R17	WEST LAKE	6 mm
L/H Front Tyre	215/55R17	WEST LAKE	6 mm
R/H Rear Tyre	215/55R17	WEST LAKE	6 mm
L/H Rear Tyre	215/55R17	WEST LAKE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.			
DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	16/12/2022	Inspection Date	19/12/2022
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 74 Kian Teck Road Singapore 628800		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	