

ASS. REC. BY:                     

REF: CS/CT122012646/Rqp3

9173

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD/TP/WS/TP RES/OD RES/EVA/INV/MV  
To inspect Vehicle No: SKS 7787L  
at Workshop n/s PERFORMANCE 1  
of 303, ALEXANDRA RD  
Insured: CTI  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: 181K  
IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
Est. Repairs: 3 days Res.: Yes or No  
Lim Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SKS 7787L Yr Regn: 2021 1 Aug  
Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or \_\_\_\_\_  
Make: B.M.W 318I ADAPTED MLC 1998  
Colour: BLUG A/C: Insured / Std / NI / NA  
Sp. Reading: 24266 T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: WBA 70M 0708 B96918  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
Brake: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
Modi: Nil / B/Rim / STD A/Rim or \_\_\_\_\_  
Tyre Size: F: 225/50R17  
R: \_\_\_\_\_  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or \_\_\_\_\_  
Front \_\_\_\_\_ Rear \_\_\_\_\_  
R/Bal. 6 mm R/Bal. 6 mm  
L/Bal. 6 mm L/Bal. 6 mm  
D.O.A. 01/12/22 D.O.I. 16/01/23  
Survey held at PERFORMANCE  
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
O/S Rear  
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair Limit - 90K

Rasul finalised final fig \$3712.10, 3 days. (Red \$1500.50, 29%)

Date/Time, File Pass to?

☐ : Preli. Report

1) 09/06 Typist

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS \$

Photos

Others

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format: MER-TP

Lump Sum / I.B.I. (\$) 3712.10

TOTAL

Dealer

**Performance Motors Limited**

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64795601 (AfterSales)  
64795624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

**E S T I M A T E****15 DEC 2022**

Estimate No. : b1 64346  
Date Estimated : 12/12/2022  
Prepared By : Foong Shiuh Jye

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -  
Quek Chia Ling (Guo JiaLing)  
18A Canberra Drive  
#07-41

Singapore 768099

- ACCOUNT - 40000  
Cash Sales - Service  
Singapore

| REGN. NO. | CHASSIS NO.       | REGN. DATE | MODEL      | MILEAGE |
|-----------|-------------------|------------|------------|---------|
| SKS7787L  | WBA70DY0708B96918 | 31/08/2021 | 318i Sedan | 11804   |

DESCRIPTION

To replace bumper rear panel and attachments

VALUE  
850 1,275.00

To spray paint bumper rear panel

986 1,058.00

To check electrical wiring system and lighting at the rear section for proper function.

168 177.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

168 177.00

Sundries.

? 80.00

Coating quotation provided by owner

? 80.00

Total Labour 1: **2,827.00**

| DESCRIPTION                              | QTY | PRIC     | VALUE    |
|------------------------------------------|-----|----------|----------|
| ✓ REAR RH LATERAL MOUNT ?                | 1   | 205.70   | 205.70   |
| TRIM STRIP (SPORT) X?                    | 1   | 96.10    | 96.10    |
| ✓ REAR RH TRIM PANEL ?                   | 1   | 99.75    | 99.75    |
| REAR BUMPER RH SIDE GUIDE ?              | 1   | 136.30   | 136.30   |
| REAR BUMPER RH SIDE GUIDE ?              | 1   | 136.30   | 136.30   |
| ✓ REAR BUMPER PANEL PRIMED (SPORT) cut ✓ | 1   | 1,280.35 | 1,280.35 |
| ✓ REAR RH REAR REFLECTOR ?               | 1   | 39.80    | 39.80    |
| DECOUPLING RING m -                      | 1   | 5.30     | 5.30     |
| ULTRASONIC SENSOR PHYTONIC BLUE WC1 ?    | 1   | 386.00   | 386.00   |

Total Parts : **2,385.60**

# Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## E S T I M A T E

|                |                   |            |        |
|----------------|-------------------|------------|--------|
| Estimate No.   | : b1 64346        | Page No. : | 2 of 5 |
| Date Estimated | : 12/12/2022      |            |        |
| Prepared By    | : Foong Shiuh Jye |            |        |

| REGN. NO. | CHASSIS NO.       | REGN. DATE | MODEL      | MILEAGE |
|-----------|-------------------|------------|------------|---------|
| SKS7787L  | WBA70DY0708B96918 | 31/08/2021 | 318i Sedan | 11804   |

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. \_\_\_\_\_ Claim No. \_\_\_\_\_

Date & Time 16/01/23 @ 12W Excess S\$ \_\_\_\_\_

Surveyor's Name Rasm Sign \_\_\_\_\_

Surveyor's Tel 9666668 Authorised Yes / No

Authorised Date \_\_\_\_\_ Time \_\_\_\_\_

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail \_\_\_\_\_

No. of Working Days Recommend 3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_



|                |   |          |
|----------------|---|----------|
| Labour 1       | : | 2,827.00 |
| Parts          | : | 2,385.60 |
| Labour 2       | : | 0.00     |
| Excess         | : | 0.00     |
| Total GST @ 7% | : | 364.88   |
| Grand Total    | : | 5,577.48 |



## Enquire PARF/COE Rebate for Registered Vehicle

|                                     |                                  |
|-------------------------------------|----------------------------------|
| <b>Vehicle Owner Particulars</b>    |                                  |
| Owner ID Type:                      | Singapore NRIC                   |
| Owner ID:                           | 917J                             |
| <b>Vehicle Details</b>              |                                  |
| Vehicle No.:                        | SKS7787L                         |
| Vehicle to be Exported:             | No                               |
| Intended Deregistration Date:       | 16 Jan 2023                      |
| Vehicle Make:                       | B.M.W.                           |
| Vehicle Model:                      | 318i ADPT LED HL                 |
| Primary Colour:                     | Blue                             |
| Manufacturing Year:                 | 2021                             |
| Engine No.:                         | F0413922B48B20A                  |
| Chassis No.:                        | WBA70DY0708B96918                |
| Maximum Power Output:               | 115.0 kW (154 bhp)               |
| Open Market Value:                  | \$41,714.00                      |
| Original Registration Date:         | 31 Aug 2021                      |
| First Registration Date:            | 31 Aug 2021                      |
| Transfer Count:                     | 0                                |
| Actual ARF Paid:                    | \$50,400.00                      |
| <b>Intended PARF Rebate Details</b> |                                  |
| PARF Eligibility:                   | Yes                              |
| PARF Eligibility Expiry Date:       | 30 Aug 2031                      |
| PARF Rebate Amount:                 | \$37,800.00                      |
| <b>Intended COE Rebate Details</b>  |                                  |
| COE Expiry Date:                    | 30 Aug 2031                      |
| COE Category:                       | E - Open - all except motorcycle |
| COE Period(Years):                  | 10                               |
| QP Paid:                            | \$64,901.00                      |
| COE Rebate Amount:                  | \$52,588.00                      |
| <b>Total Rebate Amount:</b>         | <b>\$90,388.00</b>               |

The information contained herein is correct as at 16 Jan 2023



# BMW 3 Series 318i Highline

## Overview

[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)**Price****\$181,999****Depreciation** ⓘ ⓘ

\$18,210 /yr

[View models with similar depre](#)**Reg Date**

26-Aug-2021

(8yrs 7mths 9days COE left)

**Mileage**

15,340 km (11k /yr)

**Manufactured** ⓘ

2021

**Road Tax** ⓘ

\$1,210 /yr

**Transmission**

Auto

**Dereg Value** ⓘ\$90,328 as of today ([change](#))**OMV** ⓘ

\$41,714

**COE** ⓘ

\$61,001

**ARF** ⓘ

\$50,400

**Engine Cap**

1,998 cc

**Power**

115.0 kW (154 bhp)

**Curb Weight** ⓘ

1,490 kg

**No. of Owners** ⓘ

1

**Type of Vehicle**

Luxury Sedan