



## Final Report

Estimate No. : **b1 64346**  
Date Estimated : **12/12/2022**  
Prepared By : **Foong Shiuh Jye**

Page No. :

- **ESTIMATE REPAIR FOR -**  
**Quek Chia Ling (Guo JiaLing)**  
**18A Canberra Drive**  
**#07-41**

- **ACCOUNT - 135**  
**China Taiping Insurance (S) Pte Ltd**  
**3 Anson Road**  
**#16-00 Springleaf Tower**  
**Singapore 079909**

**Singapore 768099**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
<b>SKS7787L</b>	<b>WBA70DY0708B96918</b>	<b>31/08/2021</b>	<b>318i Sedan</b>	<b>24266</b>

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace bumper rear panel and attachment include knocking out dents caused by the accident	850.00	0.00	850.00
To spray paint rear bumper	986.00	0.00	986.00
To check electrical wiring system and lightings at the rear section for proper function	168.00	0.00	168.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function	168.00	0.00	168.00
To supply ceramic coating for rear bumper (See Owner's Quotation)	80.00	0.00	80.00
Sundries	80.00	0.00	80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR RH TRIM PANEL	99.75	1.00	0.00	99.75
REAR BUMPER PANEL PRIMED (SPORT)	1,280.35	1.00	0.00	1,280.35

### # SUPPLEMENTARY ITEMS

Total Labour :	2,332.00
Total Parts :	1,380.10
Total Labour & Parts (before GST) :	3,712.10
Deduction for Excess :	
Total Repair Costs less Excess:	3,712.10
GST @8%:	296.97
Grand Total :	4,009.07

### Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269  
Co Reg No. 197401559W

