

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

15 DEC 2022

Estimate No. : b1 64346
Date Estimated : 12/12/2022
Prepared By : Foong Shiuh Jye

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Quek Chia Ling (Guo JiaLing)
18A Canberra Drive
#07-41

Singapore 768099

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKS7787L	WBA70DY0708B96918	31/08/2021	318i Sedan	11804

DESCRIPTION

To replace bumper rear panel and attachments

To spray paint bumper rear panel

To check electrical wiring system and lighting at the rear section for proper function.

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

Sundries.

Coating quotation provided by owner

VALUE

850 1,275.00

986 1,038.00

168 177.00

168 177.00

? 80.00

? 80.00

Total Labour 1: 2,827.00

DESCRIPTION

DESCRIPTION	QTY	PRIC	VALUE
✓ REAR RH LATERAL MOUNT <i>? xan</i>	1	205.70	205.70
TRIM STRIP (SPORT) <i>x an</i>	1	96.10	96.10
✓ REAR RH TRIM PANEL <i>? sca</i>	1	99.75	99.75
REAR BUMPER RH SIDE GUIDE <i>? xan</i>	1	136.30	136.30
REAR BUMPER RH SIDE GUIDE <i>? xan</i>	1	136.30	136.30
✓ REAR BUMPER PANEL PRIMED (SPORT) <i>cut</i>	1	1,280.35	1,280.35
✓ REAR RH REAR REFLECTOR <i>? xan</i>	1	39.80	39.80
DECOUPLING RING <i>x an</i>	1	5.30	5.30
ULTRASONIC SENSOR PHYTONIC BLUE WC1 <i>? xan</i>	1	386.00	386.00

Total Parts : 2,385.60

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 64346
Date Estimated : 12/12/2022
Prepared By : Foong Shiuh Jye

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKS7787L	WBA70DY0708B96918	31/08/2021	318i Sedan	11804

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
Date & Time 16/01/23 @ 12W Excess S\$ _____
Surveyor's Name Rasm Sign _____
Surveyor's Tel 9206068 Authorised Yes / No _____
Authorised Date _____ Time _____
RESURVEY PARTS PHOTO BY SURVEYOR: Yes / No PML Yes / No _____
Surveyor's E-mail _____
No. of Working Days Recommend 3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____



Labour 1	:	2,827.00
Parts	:	2,385.60
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	364.88
Grand Total	:	<u>5,577.48</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **