

Vehicle Damage Assessment Report for [SKP7730R]

Estimate Created: 21/12/2022 05:56 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 05/02/2023 23:10 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company	III	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Hyundai	Model	Santa Fe
Engine Type			
License Plate Number	SKP7730R	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- Final review base on information provide by LKK: Concluded the cost of repair at lump sum \$5200.00 with 5 days for repair

Insurlogic 5 (05/02/2023 23:08)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
FRONT BUMPER		1	688.20	-20.00 %	550.56
FRONT BUMPER SIDE RETAINER LH		1	66.50	-20.00 %	53.20
FRONT BUMPER FOGLAMP COVER LH		1	185.00	-20.00 %	148.00
FRONT BUMPER FOG LAMP LH		1	285.50	-20.00 %	228.40
FRONT BUMPER LOWER		1	366.20	-20.00 %	292.96
FRONT BUMPER CLIPS		1	40.00	-20.00 %	32.00
HEDLAMP LH		1	1150.20	-20.00 %	920.16
FRONT FENDER LH		1	585.20	-20.00 %	468.16
FRONT FENDER INNER SHIELD LH		1	265.40	-20.00 %	212.32
FRONT FENDER INNER SHIELD CLIPS		1	50.00	-20.00 %	40.00
FRONT FENDER PROTECTOR LH		1	128.00	-20.00 %	102.40
FRONT SHOCK ABSORBER LH		1	482.20	-20.00 %	385.76
FRONT KUNCKLE ARM LH		1	455.30	-20.00 %	364.24
FRONT KUNCKLE ARM BEARING LH		1	250.00	-20.00 %	200.00
FRONT LOWER ARM LH		1	520.30	-20.00 %	416.24

Parts Subtotal 4,414.40

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
FRONT SPORT RIM LH		1.0	680.00	0.00 %	680.00

Materials Subtotal 680.00

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
CHECK WIRING	RnR	20.00	0.00 %	20.00
RNR PDC SENSOR	RnR	50.00	0.00 %	50.00
RNR FRONT UNDERCARRIAGE	RnR	120.00	0.00 %	120.00
WHEEL ALIGNMENT	RnR	100.00	0.00 %	100.00

ANTI RUST	RnR	30.00	0.00 %	30.00
REPLACE/ REPAIR ACCIDENT AFFECTED ITEMS AND AREAS	RnR	500.00	0.00 %	500.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
PAINT ON ACCIDENT AFFECTED AREAS	Full spray	600.00	0.00 %	600.00

Labor Rate	S\$ 50 / Hour	General Labor Subtotal	820.00
		Paint Labor Subtotal	600.00
		Labor Subtotal	1,420.00

Summary

Repair Cost	6,514.40
Discount(20 %)	(1,314.40)
	5,200.00
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	5,200.00