

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/TMI22012649/NVY3Q2**Date:** 10/01/2023**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MN000210
<b>Claimant Vehicle No :</b>	SHC7468C	<b>Insured Vehicle No :</b>	SLQ866L
Date of Loss:	15/12/2022	Nature of Claim:	TP
		Claim No:	M2207186

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SHC7468C</b>	Engine No:	2ZRS062238
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Chassis No:	JTDKB3FU803563648
Reg. Date:	13/09/2017 (Man. Year: 2017)	Odometer:	556203 km
Colour:	Yellow		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

**CONDITION OF TYRES**

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 3 mm	Rear Left Side:	West Lake 4 mm
Front Right Side:	West Lake 3 mm	Rear Right Side:	West Lake 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,723.93	3,285.64	438.29	11.77
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,360.00	630.00	730.00	53.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,094.93</b>	<b>3,926.64</b>	<b>1,168.29</b>	<b>22.93</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,150.00</b>		
<b>(S\$)</b>	5,094.93	3,150.00	1,944.93	38.17
<b>+ GST 7.00/7.00% (S\$)</b>	356.65	220.50	136.15	38.17
<b>Nett Amount (S\$)</b>	<b>5,451.58</b>	<b>3,370.50</b>	<b>2,081.08</b>	<b>38.17</b>

**INSPECTION**

Date of Assignment:	19/12/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	16/12/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

**Adjuster:** Muhammad Nazril Bin Abdullah**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 10 Jan 2023)
<b>Parts:</b> 144	TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SHC7468C)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER ASSY	Buckled	586.18 FL	*586.18 FL
2	1		*FRONT BUMPER LOWER GRILLE	Serviceable	193.18 FL	*- FL
3	10		*BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
4	1		*BUMPER SPONGE RH	Serviceable	115.70 FL	*- FL
5	1		*BUMPER BRACKET RH	Serviceable	77.00 FL	*- FL
6	1		*BUMPER EMBLEM	Necessary	86.50 FL	*86.50 FL
7	1		*BUMPER TOW COVER RH	Scratched	28.38 FL	*28.38 FL
8	1		*HEAD LAMP RH	Cracked	2,637.80 FL	*2,637.80 FL
9	1		*FOG LAMP RH	Scratched	920.00 FL	*920.00 FL
10	1		*FRONT FENDER SHIELD RH	Serviceable	198.50 FL	*- FL
11	1		*FRONT FENDER ADVERTISEMENT	Necessary	100.00 FL	*100.00 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,965.24</b>	<b>4,380.86</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	1,241.31	1,095.22
<b>Total Parts (\$\$)</b>	<b>3,723.93</b>	<b>3,285.64</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	OD/TP Case (Insurer)	11.00	11.00
<b>Sub Total (\$\$)</b>			<b>11.00</b>	<b>11.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	700.00	350.00
2	SPRAY PAINTING	New	600.00	250.00
3	CHECK LIGHTING AND WIRING	New	60.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,360.00</b>	<b>630.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**