

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012652/RWP3Q2**Date:** 30/01/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00238992100
Claimant Vehicle No :	SLL4954R	Insured Vehicle No :	SLW9977J
Date of Loss:	13/12/2022	Nature of Claim:	TP
		Claim No:	SNM22D209022/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLL4954R	Engine No:	L15B4409134
Make & Model:	HONDA VEZEL, 1.5 (A)	Chassis No:	RU11209134
Reg. Date:	28/02/2017 (Man. Year: 2016)	Odometer:	133230 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,330.00	1,896.00	434.00	18.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,780.00	750.00	1,030.00	57.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,110.00	2,646.00	1,464.00	35.62
Approved Total (Overridden) (\$\$)		2,100.00		
(\$\$)	4,110.00	2,100.00	2,010.00	48.91
+ GST 7.00/7.00% (\$\$)	287.70	147.00	140.70	48.91
Nett Amount (\$\$)	4,397.70	2,247.00	2,150.70	48.91

INSPECTION

Date of Assignment:	19/12/2022		
Date Inspected:	19/12/2022	Inspected At:	ETHOZ Protect Pte Ltd (Bukit Batok) 30 Bukit Batok Crescent Singapore 658075
Estimated Period of Repair:	4.0 days		

Adjuster: MOHD RASUL**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Jan 2023)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLL4954R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	860.00 FL	*860.00 FL
2	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
3	1		*TAILGATE	Buckled	1,180.00 FL	*1,180.00 FL
4	2		*REAR WINDSCREEN MOULDING	Necessary	54.00 FL	*54.00 FL
5	1		*REAR LOGO	Not Necessary	35.00 FL	*- FL
6	1		*EMBLEM -VEZEL	Necessary	58.00 FL	*58.00 FL
7	1		*TAILGATE LOCK	Not Necessary	220.00 FL	*- FL
8	1		*TAILGATE WEATHERSTRIP	Necessary	118.00 FL	*118.00 FL
9	1		*END PANEL (NPA)	Not Necessary	0.00 FL	*- FL
10	1		*REVERSE SENSOR	Not Necessary	220.00 FS	*- FS
11	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$\$)	2,845.00 2,360.00
					- List Item Discount on L Items 20.00/20.00% (\$\$)	515.00 464.00
					Total Parts (\$\$)	2,330.00 1,896.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO FACILITATE REPAIR	New	800.00	400.00
2	TO RESPRAY AFFECTED AREAS	New	800.00	200.00
3	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	150.00	120.00
4	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New	30.00	30.00
Gross Labour Cost (\$\$)			1,780.00	750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >