

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLL 4954Rat Workshop no/s ETH02of 30, BUKIT BATU CRESCENTInsured: CTI

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 56K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLL 4954R Yr Regn: 2017 / FEBType: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: Honda V2XL 1.5XCVT cc 1496Colour: White A/C: ☒ Insured / ☐ Std / ☐ NI / ☐ NASp. Reading: 133230 T/Radio: ☒ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: _____

C/No: RM1209134Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: ☒ Nil / ☐ SRim / ☐ STD A/Rim orTyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FALKEN

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 13/12/22 D.O.I. 19/12/22Survey held at ETH02Des. of Damages: ☒ Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ UIC / ☐ Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction

REPAIR LIMIT - 26K

Date/Time, File Pass to?

☐ : Prefl. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee: _____

2)

Add Fee: ☐ : Site Insp (\$ _____)

Transportation: _____

☐ : Interview (\$ _____)

S + RS _____ SI

☐ : Tech. Invs (\$ _____)

Photos

☐ : Weekend (\$ _____)

Others

Report Format : _____

Lump Sum / I.B.I. (\$) _____

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Selamatshahh
CLAIM DEPARTMENT
DID : 66547519
FAX :

Date : 16/12/2022

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
ESTIMATION

Attn : Motor Claim Department FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1

Accident Date : 13/12/2022

Vehicle No : SLL-4954-R

Make & Model : HONDA VEZEL 1.5X I-VTEC (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
-----	-------------	-------------------	---------------

List Item

1	REAR BUMPER <i>de</i>	860.00
10	REAR BUMPER CLIPS <i>me</i>	50.00
1	TAILGATE <i>bu</i>	1,180.00
2	REAR WINDSCREEN MOULDING <i>me</i>	54.00
1	REAR LOGO <i>me</i>	35.00
1	EMBLEM - VEZEL <i>me</i>	58.00
1	TAILGATE LOCK <i>X</i>	220.00
1	TAILGATE WEATHERSTRIPE <i>me</i>	118.00
1	END PANEL <i>me</i>	

RESTORE

Date : 16/12/2022

To : **CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.**
ESTIMATION

Attn : **Motor Claim Department**

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1

Accident Date : 13/12/2022

Vehicle No : SLL-4954-R

Make & Model : HONDA VEZEL 1.5X I-VTEC (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	2575.00	
	Discount 20% On Parts	(515.00)	
	<u>Special Nett Item</u>		
1	REVERSE SENSOR ?	220.00	
1	REAR WINDSCREEN SEALANT ne /	50.00	40
	Sub Total	270.00	
	<u>Labour & Misc</u>		
	LABOUR TO FACILITATE REPAIR	800.00	400
	TO RESPRAY AFFECTED AREAS	800.00	200
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	150.00	120

Date : 16/12/2022

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1 Accident Date : 13/12/2022

Vehicle No : SLL-4954-R Make & Model : HONDA VEZEL 1.5X I-VTEC (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	30.00	
	Sub Total	1780.00	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Remarks:

*9/p before paint
4 days - 1/13 - Resy after repair*

4,110.00

SUB TOTAL

GST 7.0 % 287.70

TOTAL 4,397.70

Surveyor's name:

Rasul - Hp 90010068

Principal's name: ETHOZ Group Ltd

Survey Date & Time:

19/12/22 P 1535

> Back to OneMotorling

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	943G
Vehicle No.:	SLL4954R
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Dec 2022
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	L15B4409134
Chassis No.:	RU11209134
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$21,894.00
Original Registration Date:	28 Feb 2017
First Registration Date:	28 Feb 2017
Transfer Count:	1
Actual ARF Paid:	\$12,652.00

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Feb 2027
PARF Rebate Amount:	\$8,856.00

COE Expiry Date:	27 Feb 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,430.00
COE Rebate Amount:	\$20,698.00
Total Rebate Amount:	\$29,554.00

The information contained herein is correct as at 20 Dec 2022

OK

Honda Vezel 1.5A X

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price	\$56,800		
Depreciation 	\$12,140 /yr View models with similar depre	Reg Date	25-Feb-2017 (4yrs 2mths 4days COE left)
Mileage	N.A.	Manufactured 	2016
Road Tax 	\$682 /yr	Transmission	Auto
Dereg Value 	\$29,116 as of today (change)	OMV 	\$21,466
COE 	\$49,430	ARF 	\$12,053
Engine Cap	1,496 cc	Power	96.0 kW (128 bhp)
Curb Weight 	1,190 kg	No. of Owners 	2
Type of Vehicle	SUV		