

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

TP Sampo
xin/ya

ESTIMATE

Vehicle No : SLR 9294 Y

Chassis No: WVWZZZ16ZGM019810

Make/Model : VOLKSWAGEN JETTA

Accident date : 16.12.2022

No	DESCRIPTION	Qty	Amount (S\$)
List Items			
1	Front bumper <i>Detached</i>	1	\$ 1247.
2	Front bumper side holder <i>@ \$ Detached</i>	1	\$ 75
3	Front bumper lower grille <i>new</i>	1	\$ 168
4	Front RH fender <i>Detached</i>	1	\$ 571
5	Front RH fender inner shield <i>Detached</i>	1	\$ 198
6	Front RH headlamp <i>at</i>	1	\$ 1955
7	Front RH shock absorber <i>Best</i>	1	\$ 488
8	Front RH knuckle arm <i>Detached</i>	1	\$ 425
9	Front RH knuckle arm bearing <i>new</i>	1	\$ 398
10	Front RH linkage <i>new</i>	1	\$ 149
11	Front RH drive shaft	1	\$ 1680
12	Front RH lower arm <i>Best</i>	1	\$ 445

5802

Less 10% Disc

5221.80

Total

Special Nett Items

1	Front RH sport rim <i>at</i>	1	\$ 800.00
2	Front RH tyre <i>new</i>	1	\$ 300.00
3	Front RH fender inner shield clips (1 set) <i>new</i>	1	\$ 60.00
4	Front bumper clips (1 set) <i>new</i>	1	\$ 60.00
Total			\$ 1,220.00

680

Labour Cost

1	To check wheel alignment	\$ 100.00
2	Remove & refix front suspension	\$ 500.00
3	Remove, replace & repair consistent to the accident	\$ 1,100.00
4	Respray painting	\$ 1,000.00
5	Tuff kote	\$ 100.00
Total		\$ 2,800.00

1260

Grand Total

\$

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 7261.80

1/5: 5.8K.

06 Days.

5.8K