

ASS. REC. BY:

REF:

C72/22012659/KP

C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

1-B.1%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHF 2792

Yr Regn:

12.19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius

c.c

1788

Colour

M. Brown

A/C:

Insured / Std / NI / NA

Sp. Reading

171872

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB31F4 003089467

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

5

mm

L/Bal.

7

mm

L/Bal.

5

mm

D.O.A.

15/12/22

D.O.I.

15/12/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

19/12/22 144.33 Carh

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

F. Inds

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$



Case Details

Case Reference Number :

TAX/12/22/2035

Type of Repair : Accident Repair

Vehicle Registration Number : SHF279L

Company Type : Strides Taxi Pte Ltd

Estimation ID : EST-20078-ID

Assigned By : Taxi Claims Manager Team

Insurance Company Name : China Taiping Insurance (Singapore) Pte Ltd

Accident Date and Time : 15/12/2022 12:00 AM

Vehicle Age(In Months) : -

Documents / Photographs

View Documents / Photographs

Total Documents: 0

Estimation Details


Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation					Surveyor Approval					Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
Standard	Main			COVER, FR BUMPER	1	565.60	565.60	25.00	424.20	Replace	1	0	Repair	
Standard	Main			SUPPORT, FR BUMPER RH	1	86.20	86.20	25.00	64.65	Replace	0	0	Not Give	
Standard	Main			CLIPS PIECE, FRT & RR BUMPER	10	4.80	48.00	25.00	36.00	Replace	0	0	Check	
Standard	Main			UNIT, HEADLAMP, RH	1	2,852.40	2,852.40	10.00	2,567.16	Replace	0	0	Not Give	
Standard	Main			FENDER SUB-ASSY, FR, RH	1	1,060.70	1,060.70	25.00	795.53	Replace	1	0	Repair	
Standard	Main			EMBLEM, SIDE PANEL (HYBRID)	1	59.10	59.10	25.00	44.33	Replace	1	44.33	Replace	me ✓
Standard	Main			LINER, FR FENDER, RH	1	219.10	219.10	25.00	164.33	Replace	0	0	Not Give	
Total Spare Part Cost									4,096.20	Surveyor Total 44.33				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0				
Final Spare Part Cost									4,096.20	Final Sur Total 44.33				

Labour's Cost Detail

S.No.	Costing Type	Job Scope
1	Main	TO REPAIR RH FRONT PORTION
Total:		676.00

Spray Cost Detail



Estimator Assesment(\$)

Surveyor Assesment(\$)

Survey Date

15/12/2022