


Section A - Accident Details

Registration Number	SHF279L
Case Reference Number	TAX/12/22/2035
Registration Date	26/12/2019
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	NG THIAN CHYE
Type of Accident	Side Swipe
Accident Date and Time	15/12/2022 8:00 AM
Accident Reported Date and Time	15/12/2022 9:45 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24117156
Special Instruction to ARC, if any	TP/ RIGHT FRONT PORTION/CHINA TAIPING - LKK
Prepared Date and Time	15/12/2022 11:01 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$200.00
Total Spray Cost	\$756.00	\$400.00
Total Spare Part Cost	\$4,096.20	\$44.33
Total Other Cost	\$380.00	\$0.00
TOTAL COST	\$5,908.20	\$644.33 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	2.0
Prepared / Adjusted By	Boon Chew Tay	Kenneth Kong (LKK) / China Taiping
ARC / Surveyor Sign Off Date	15/12/2022 2:51 PM	15/12/2022 2:35 PM
Signature		Ken
Remarks		AFTER REPAIR PHOTO , FOR CHECK ITEM

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2301-0262	Invoice Number	
Quotation Date	18.01.2023	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH FRONT PORTION	\$676.00	\$200.00
Total Labour	\$676.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$756.00	\$400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$380.00	\$0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47980	COVER, FR BUMPER	1.00	\$565.60	100.00	\$0.00	Replace	Repair
		52115-47050	SUPPORT, FR BUMPER RH	0.00	\$86.20	0.00	\$0.00	Replace	Not Given
		52161-16010	CLIPS PIECE, FRT & RR BUMPER	0.00	\$4.80	0.00	\$0.00	Replace	Check
		81145-47890	UNIT, HEADLAMP, RH	0.00	\$2,852.40	0.00	\$0.00	Replace	Not Given
		53801-47080	FENDER SUB-ASSY, FR, RH	1.00	\$1,060.70	100.00	\$0.00	Replace	Repair
		75374-47140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$59.10	25.00	\$44.33	Replace	Replace
		53875-47120	LINER, FR FENDER, RH	0.00	\$219.10	0.00	\$0.00	Replace	Not Given
Total					\$4,847.90		\$44.33		

R
X
X
X
X
R
√
X

} nn
nec
nn

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

44.33
+ 200.00
+ 400.00

644.33