

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SJQ 4522Bat Workshop m/s AP.

of

Insured: SMX 73744

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.Bal. or Market Value: 13k.

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 5 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

941h

Vehicle: IN / OUT

Date: _____

Person Contacted: 17493570Veh No: SJQ 4522BYr Regn: 12/05/09Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CA /Make: Toyota PremioC.C. 1496Colour: maroonA/C: Insured / Std / NI / NASp. Reading: 308767T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: N2T2603036584Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt or affectedBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55-16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PR / SUMI /

TOYO / YOKO or

Front: 6Rear: 6

R/Bal. _____ mm

R/Bal. _____ mm

L/Bal. 6 mmL/Bal. 6 mmD.O.A. 18/12/22D.O.I. 19/12/22

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orThe U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Rep 9500col used 30-04-2024Nett 89430have find28/12/22 1/5 @ 6700 in hand Alan.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐

Site Insp (\$

) S + RS, SI☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format : _____

Lump Sum / I.B.I.: (\$ _____)

TOTAL

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 200006262D

VEHICLE No: SJQ 4522B

H SIAO Tany

Not Arthur
LHK
19/12/22
2/5 \$6700/
interim payment
5 days

1PC	FRONT BUMPER	car/torn	1150.20	\$1,681.10	✓
1PC	FRONT BUMPER SIDE RETAINER O/S	surf		\$90.00	✓
1PC	FRONT BUMPER CENTRE GRILLE	17		\$108.00	X
1PC	FRONT BUMPER BEAM	17		\$561.10	X
1PC	FRONT BUMPER SPONGE	17		\$140.10	X
1SET	FRONT BUMPER CLIPS	17		\$50.00	✓
1PC	HEADLAMP O/S	17		\$1,980.00	X
1PC	FRONT BRACE PANEL	17		\$121.00	X
1PC	FRONT FENDER O/S	should	891.20	\$1,522.00	✓
1PC	FRONT FENDER INNER O/S	Body	299.50	\$322.00	✓
1PC	FRONT FENDER INNER VERTICAL GARNISH O/S	Torn		\$118.10	✓
1SET	FRONT FENDER INNER SHIELD CLIPS O/S	Twl		\$50.00	✓
1PC	FRONT SUPPORT PANEL	17		\$1,160.00	X
1PC	FRONT SUPPORT PANEL TOP GARNISH	17		\$210.00	X
1SET	FRONT SUPPORT PANEL TOP GARNISH CLIPS	17		\$50.00	X
1PC	WIPER WASHER TANK	17		\$182.00	X
1PC	ROCKER PANEL GARNISH O/S	17		\$991.00	X
1SET	ROCKER PANEL GARNISH CLIPS O/S	17		\$50.00	X
1PC	FRONT SHOCK ABSORBER O/S	Bent		\$485.10	✓
1PC	FRONT LOWER ARM O/S	Bent		\$671.80	✓
1PC	FRONT KNUCKLE ARM O/S	Bent		\$545.80	✓
1PC	FRONT KNUCKLE ARM BEARING O/S	Damage	285.50	\$355.10	✓
1PC	FRONT DRIVE SHAFT O/S	17		\$1,488.20	X
1SET	FRONT SPORT RIM	worped	500 S/N	\$1,250.00	1pc
1PC	FRONT DOOR O/S	Body		\$1,650.10	✓
1PC	FRONT DOOR OUTER PROTECTOR O/S	Bent		\$288.90	✓
1PC	FRONT DOOR HINGE LOWER O/S	Bent		\$105.00	✓
1PC	FRONT DOOR CHECKER O/S	17		\$166.00	X
1SET	FRONT DOOR FRAME BLACK STICKER O/S	17		\$80.00	✓
1PC	FRONT DOOR INNER RUBBER O/S	17		\$211.80	X
1PC	FRONT DOOR INNER TRIM BOARD O/S	17		\$855.10	X
1PC	FRONT DOOR OUTER PILLAR O/S	20/Bent	257	\$989.10	✓
				\$18,528.40	

TO CHECK WIRING
TO RESET & REPROGRAMME SYSTEM
TO DISMANTLE & REFIX FRONT UNDER CARRIAGE
TO CONDUCT WHEEL ALIGNMENT
TO REFILL AIR CON GAS
TO TRANSFER FRONT DOOR MECHANISM
TO SPRAY RUST PROOFING

\$50.00 20
17 \$100.00 X
\$360.00 150
\$100.00 80
17 \$100.00 X
\$80.00 60
\$200.00 80

LABOUR FOR PANEL BEATING & REPLACED PARTS
TO PUTTY & SPRAY PAINTING

	\$1,100.00	700
	\$1,200.00	1000
TOTAL	\$26,164.40	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-7750.3
252
5812.72
500
2090
8402.12
6722

COMPUTERISED 4 WHEEL ALIGNMENT HUNTER DSP700

Company: FASTECH AUTO PTE LTD
VIN: SJQ 4522 B
Date: 19.12.22 10:39



SJQ 4522 B

TOYOTA AXIO

Front : Left

Actual	Before	Specified Range
-1°04'	-1°05'	-1°15' 0°15'
2°59'	2°59'	2°20' 3°50'
-0°13'	-0°14'	-0°03' 0°08'
16°07'	16°07'	10°30' 12°00'
15°02'	15°02'	9°15' 12°15'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-1°54'	-1°54'	-1°15' 0°15'
2°54'	2°54'	2°20' 3°50'
-0°12'	-0°11'	-0°03' 0°08'
12°52'	12°52'	10°30' 12°00'
10°58'	10°58'	9°15' 12°15'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
0°50'	0°49'	-0°45' 0°45'
0°05'	0°05'	-0°45' 0°45'
3°15'	3°15'	
-0°25'	-0°25'	-0°05' 0°16'

Rear : Left

Actual	Before	Specified Range
-1°29'	-1°29'	-2°00' -1°00'
0°03'	0°03'	0°00' 0°11'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°20'	-1°20'	-2°00' -1°00'
0°07'	0°07'	0°00' 0°11'

Rear

Cross Camber
Total Toe
Thrust Angle
Axle Offset

Actual	Before	Specified Range
-0°08'	-0°08'	-0°30' 0°30'
0°10'	0°11'	0°00' 0°21'
-0°02'	-0°02'	
0mm	0mm	