



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2302438

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 18/04/2023
Reference CC3/CTI22012666/Kya3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHB 1700B
Insured Veh. SKL 3843X
Claim No. SNM22D209134/C02
Policy No. DMHCSNW00008172200
Accident Date 14/12/2022
Inspection Date 15/12/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI22012666/Kya3q2 Date: 18/04/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SKL 3843X	Veh. Inspected	SHB 1700B
	Policy No.	DMHCSNW00008172200	Coverage (\$)	0.00
	Claim No.	SNM22D209134/C02	Excess (\$)	0.00
	Assign From		Assign Date	15/12/2022
2. Vehicle Particulars & Condition				
	Make & Model	M.G. MG5 (A)	c.c	0
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	LSJE24035MG058568	Colour	GREEN
	Odometer	2863 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/60 R16	BRIDGESTONE	9 mm
	L/H Front Tyre	205/60 R16	BRIDGESTONE	9 mm
	R/H Rear Tyre	205/60 R16	BRIDGESTONE	9 mm
	L/H Rear Tyre	205/60 R16	BRIDGESTONE	9 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	14/12/2022	Inspection Date	15/12/2022
	Survey held at	STRIDES AUTOMOTIVE SERVICES PL. 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 1700B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FASCIA-RR BPR LWR (DISC 10%)	DENTED	230.68	207.61
2	SCRIVET-RR BPR FASCIA @\$0.84 (DISC 10%)	NECESSARY	1.68	1.51
1	LAMP ASM-RR FOG - LH (DISC 10%)	CRACKED	36.30	32.67
1	BAR ASM-RR BPR IMP (DISC 10%)	BENT	339.77	305.79
1	PANEL ASM-RR END	NOT NECESSARY	708.66	-
1	FINISHER-RR BPR - RH	NOT NECESSARY	47.42	-
1	FINISHER-RR BPR - LH	NOT NECESSARY	47.42	-
1	BRACKET ASM-RR BPR FASCIA SI-RH	NOT NECESSARY	29.85	-
1	BRACKET ASM-RR BPR FASCIA SI	NOT NECESSARY	29.85	-
1	BRACKET-RR BPR FASCIA SI MTG - RH	NOT NECESSARY	46.08	-
1	BRACKET-RR BPR FASCIA SI MTG - LH	NOT NECESSARY	46.08	-
1	BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST	NOT NECESSARY	13.20	-
1	BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST	NOT NECESSARY	12.90	-
1	BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST	NOT NECESSARY	12.90	-
1	BRACKET-RR BPR FASCIA LWR MTG - RH	NOT NECESSARY	12.80	-
1	BRACKET-RR BPR FASCIA LWR MTG - LH	NOT NECESSARY	12.80	-
1	BAR ASM-RR BPR IMP	NOT NECESSARY	339.76	-
1	LAMP ASM-RR FOG - RH	NOT NECESSARY	189.07	-
1	SENSOR-RR PARK DIST CONT	NOT NECESSARY	65.00	-
1	FASCIA-RR BPR	TO REPAIR SEE LABOUR	758.48	-
			2,980.70	547.58
	<u>LABOUR</u>			
	PANEL BEATING AND BODY WORK. INCLUSIVE OF THE REPAIR OF FASCIA-RR BPR.		1,200.00	450.00
	SPRAY PAINT.		888.00	400.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO CHECK WIRING AND SYSTEM FUNCTION.		120.00	20.00

Report Ref No. CC3/CTI22012666/Kya3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY RUST-PROOFING ON AFFECTED AREA.	NOT NECESSARY	100.00	-
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	50.00
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO CHECK & RESET SYSTEM FUNCTION.		350.00	150.00
	ISOLATED OF (EV) (NET).		150.00	150.00
			3,088.00	1,220.00
GRAND TOTAL			6,068.70	1,767.58

RECOMMENDED COST OF REPAIRS				1,767.58
------------------------------------	--	--	--	-----------------

Report Ref No. CC3/CTI22012666/Kya3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHB 1700B

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHB 1700B

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHB 1700B

RE-INSPECTION

