

ASS. REC. BY:

REF:

C12 / 22012888/KP

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.: Yes or No

Lum Sum:

1-B.1

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

9/1 81787.58

Cuh

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation

S - RS. SI

Fees

Others

TOTAL

Veh No:

S14B 1700B

Yr Regn:

11, 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MG

MG5

C.C

Colour

Green

A/C: Insured / Std / NI / NA

Sp. Reading

2883

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

LSTE 24035MG 058568

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

205/80R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

14/12/22

D.O.I.

15/12/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.



Case Details

Case Reference Number : TAX/12/22/2034
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB1700B

Company Type : Strides Taxi Pte Ltd
 Estimation ID : EST-20072-ID
 Assigned By : Tan Lee Ge #

Insurance Company Name : China Taiping Insurance (Singapore) Pte Ltd
 Accident Date and Time : 14/12/2022 07:35 AM
 Vehicle Age(In Months) : -

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation												Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			PANEL ASM-RR END	1	708.66	708.66	10.00	637.79	Replace	0	0	<i>R</i> Not Give	
Standard	Main			FASCIA-RR BPR	1	758.48	758.48	10.00	682.63	Replace	1	0	Repair	
Standard	Main			FASCIA-RR BPR LWR	1	230.68	230.68	10.00	207.61	Replace	1	207.61	Replace	<i>Det</i>
Standard	Main			FINISHER-RR BPR - RH	1	47.42	47.42	10.00	42.68	Replace	0	0	Not Give	
Standard	Main			FINISHER-RR BPR - LH	1	47.42	47.42	10.00	42.68	Replace	0	0	Not Give	
Standard	Main			BRACKET ASM-RR BPR FASCIA SI-RH	1	29.85	29.85	10.00	26.87	Replace	0	0	Check	
Standard	Main			BRACKET ASM-RR BPR FASCIA SI	1	29.85	29.85	10.00	26.87	Replace	0	0	Check	
Standard	Main			BRACKET-RR BPR FASCIA SI MTG - RH	1	46.08	46.08	10.00	41.47	Replace	0	0	Check	
Standard	Main			BRACKET-RR BPR FASCIA SI MTG - LH	1	46.08	41.47	10.00	41.47	Replace	0	0	Check	
Standard	Main			BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST CONT SEN) - LH	1	13.20	13.20	10.00	11.88	Replace	0	0	Not Give	
Standard	Main			BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST CONT SEN) - CTE	1	12.90	12.90	10.00	11.61	Replace	0	0	Not Give	
Total Spare Part Cost									2,493.83	Surveyor Total			241.79	
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)			0	
Final Spare Part Cost									2,493.83	Final Sur Total			241.79	

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST CONT SEN) - RH	1	12.90	12.90	10.00	11.61	Replace	0	0	Not Give	▼
Standard	Main			BRACKET-RR BPR FASCIA LWR MTG - RH	1	12.80	12.80	10.00	11.52	Replace	0	0	Check	▼
Standard	Main			BRACKET-RR BPR FASCIA LWR MTG - LH	1	12.80	12.80	10.00	11.52	Replace	0	0	Check	▼
Standard	Main			BAR ASM-RR BPR IMP	1	339.76	339.76	10.00	305.78	Replace	0	0	Check	▼ ✓
Standard	Main			SCRIVET-RR BPR FASCIA	2	0.84	1.68	10.00	1.51	Replace	2	1.51	Replace	▼ ✓
Standard	Main			LAMP ASM-RR FOG - RH	1	189.07	189.07	10.00	170.16	Replace	0	0	Not Give	▼
Standard	Main			LAMP ASM-RR FOG - LH	1	36.30	36.30	10.00	32.67	Replace	1	32.67	Replace	▼ ✓
Standard	Main			SENSOR-RR PARK DIST CONT	3	65.00	195.00	10.00	175.50	Replace	0	0	Not Give	▼
Total Spare Part Cost									2,493.83	Surveyor Total 241.79				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)				
Final Spare Part Cost									2,493.83	Final Sur Total 241.79				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	900.00	250.00	
Total:			900.00	250.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	428.00	200	
2	Main	TO RESPRAY REAR PANEL	230.00	200.00	
Total:			658.00	200.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0	
Total:			1,000.00	370.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	20	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0	
4	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	50	
5	Main	TO REPLACE SUNDRY PARTS	100.00	0	
6	Main	TO CHECK & RESET SYSTEM FUNCTION	350.00	150	
7	Main	ISOLATED OF (EV) (NET)	150.00	150.00	
Total:			1,000.00	370.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	2,493.83	241.79
Total Labour Cost	900.00	250.00
Total Spray Painting	658.00	200.00
Other	1,000.00	370.00
Overall Total	5,051.83	1,061.79
Lump Sum Repair Option	☐	☐
Lump Sum Total	0.00	1,061.79
Surveyor Approved Amount		1,061.79
No of Repair Days*	5	3
Remarks	-	AFTER REPAIR PHOTO . FOR CHECK ITEM and REPLACE
Surveyor Name		Kenneth Kong (LKK)

Signature

Survey Date

Ken

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Save

Clear