

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIS22012673/APA3Q2**Date:** 27/06/2023**REFERENCE**

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2003578850
<b>Claimant Vehicle No :</b>	SMW6079J	<b>Insured Vehicle No :</b>	SGM3323Y
Date of Loss:	14/12/2022	Nature of Claim:	TP
		Claim No:	202222008919

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMW6079J</b>	Engine No:	CZDC11272
Make & Model:	AUDI Q3, 1.4 TFSI (A)	Chassis No:	WAUZZZF37M1028863
Reg. Date:	27/11/2020 (Man. Year: 2020)	Odometer:	25242 km
Colour:	Blue		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	215/65 R17	Rear Tyre Size:	215/65 R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,182.00	1,120.60	5,061.40	81.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,752.00	2,152.00	600.00	21.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>8,934.00</b>	<b>3,272.60</b>	<b>5,661.40</b>	<b>63.37</b>
<b>+ GST 8.00/8.00% (S\$)</b>	714.72	261.81	452.91	63.37
<b>Nett Amount (S\$)</b>	<b>9,648.72</b>	<b>3,534.41</b>	<b>6,114.31</b>	<b>63.37</b>
<b>+ Car Rental (3.0 x S\$100.00/day) (S\$)</b>		300.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>3,836.41</b>		

**INSPECTION**

Date of Assignment:	15/12/2022		
Date Inspected:	29/12/2022	Inspected At:	Premium Automobiles Pte Ltd (HQ) 55 UBI ROAD 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Jun 2023)
Parts:	M1-SUV	AUDI Q3 1.4 TFSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMW6079J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,738.00 FS	*- FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	220.00 FS	*- FS
3	1		*REAR BUMPER SPOILER	Torn	510.00 FS	*510.00 FS
4	1		*REAR BUMPER TOW EYE COVER	Not Necessary	48.00 FS	*- FS
5	1		*REAR BUMPER CROSS REINFORCEMENT -CENTER	Not Necessary	108.00 FS	*- FS
6	1		*REAR BUMPER BRACKET	Not Necessary	53.00 FS	*- FS
7	1		*REAR BUMPER REFLECTOR LH	Cracked	46.00 FS	*45.60 FS
8	1		*REAR BOOT LID OPENING CONTROL UNIT	Not Necessary	484.00 FS	*- FS
9	1		*REAR TAILGATE OPENING SENSOR LINE	Not Necessary	228.00 FS	*- FS
10	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	693.00 FS	*- FS
11	2		*REAR BUMPER HOLDING STRAP -LH/RH	Not Necessary	64.00 FS	*- FS
12	1		*REAR BUMPER GUIDE SECTION -LH	Not Necessary	71.00 FS	*- FS
13	2		*REAR PARKING AID SENSOR -INNER /OUTER	Not Necessary	531.00 FS	*- FS
14	4		*REAR PARKING AID SEAL RING	Not Necessary	10.00 FS	*- FS
15	1		*SET REAR BUMPER WIRING	Not Necessary	449.00 FS	*- FS
16	2		*REAR WHEEL COVER -LH/RH	Necessary	566.00 FS	*565.00 FS
17	1		*REAR UNDERBODY TRIM -LH	Not Necessary	63.00 FS	*- FS
18	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
Total Parts (S\$)					6,182.00	1,120.60

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER .RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,200.00	800.00
3	TO RESPRAY REAR BUMPER	New	1,000.00	800.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,752.00</b>	<b>2,152.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >