
PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE

ACCIDENT REPAIRS

WORKSHOP

: UBI ROAD 1 : 6366 2323

CONTACT NO

: 6841 1183

FAX NO

00411105

REFERENCE

PA/TP/1129/2022/EQ

DATE

: 16-Dec-22

WIP

54996

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 29/12/2022

YOUR INSURED VEH NO: SGM 3323 Y

Allianz Insurance Singapore Pte Ltd

79 Robinson Road

#09-01

Singapore 068897

Attn: Motor Claims Dept

OWNER'S NAME

MR ANG CHEE WEI

ADDRESS

2 RIVERVALE LINK

#15-03

SINGAPORE 545040

TELEPHONE

HP +65 96150848

TYPE OF CLAIM

: THIRD PARTY CLAIM

POLICY NO

2070167923-02

VEHICLE NO

SMW 6079]

MODEL CODE

: AUDI Q3 1.4 TFSI S-TRONIC

MODEL YEAR

27/11/2020

ENGINE NO

CZD C11272

CHASSIS NO

: WAUZZZF37M1028863

MILEAGE

: .

DATE IN

. .

ESTIMATED BY

JOHNNY BOO / ALLAN WU

ACCIDENT DATE

14-Dec-22

PLACE OF ACCIDENT

: 14-Dec-22

: OUT FROM SUNTEC CITY ONTO NICOLL HIGHWAY





55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMW 6079]

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N	\$ 360.00	/
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		\$ 1,200.00	800 ✓
3	TO RESPRAY REAR BUMPER.		\$ 1,000.00	800 V
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	\$ 192.00	\
	TOTAL LABOUR CHARGES		\$ 2,752.00	





55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 6079]

DAMAGED PARTS & PRICES

5/N	PARTS DESCRIPTION	QTY		S/NETT	REMARKS
1	REAR BUMPER Repris	1	\$	1,738.00 *	•
2	REAR BUMPER FIXING PARTS Not wer	1	\$	220.00 /	,
3	REAR BUMPER SPOILER Ton	1	\$	510.00	V
4	REAR BUMPER TOW EYE COVER ***	1	\$	48.00	
5	REAR BUMPER CROSS REINFORCEMENT - CENTER WE am	1	\$	108.00 📌	
6	REAR BUMPER BRACKET Me M	1	\$	53.00 *	
7	REAR BUMPER REFLECTOR - LH Cracked.	1	\$	46.00	45.60
8	REAR BOOT LID OPENING CONTROL UNIT }	1	\$	484.00 🗡	
9	REAR TAILGATE OPENING SENSOR LINE	1	\$	228.00	
10	REAR BUMPER REINFORCEMENT BEAM	1	\$	693.00	X
11	REAR BUMPER HOLDING STRAP - LH / RH	2	\$	64.00 ×	
12	REAR BUMPER GUIDE SECTION - LH	1	\$	71.00	
13	REAR PARKING AID SENSOR - INNER / OUTER	2	\$	531.00	:
14	REAR PARKING AID SEAL RING ? NE NE	4	\$	10.00 *	
15	REAR BUMPER WIRING SET	1	\$	449.00 ⊀	
16	REAR WHEEL COVER - LH / RH Mer	2	\$	566.00	565.00
17	REAR UNDERBODY TRIM - LH	1	\$	63.00 🗶	
18	SUNDRIES ? XNN		\$	300.00	×
	TOTAL SPARE PARTS	:	\$	6,182.00	
	TOTAL LABOUR CHARGES	:	\$	2,752.00	
	GRAND TOTAL	14. 15.	\$ 1	8,934.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

: Not Authorised, 03 Days.

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE

AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER

LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.

FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR

APPOINTMENT.

YOURS FAITHFULLY, PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY 500 BODY REPAIR MANAGER ALLAN WU CLAIMS CONSULTANT