

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI22012678/NVY3Q2**Date:** 10/01/2023REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MN000293	
Claimant Vehicle No :	SHC1800R	Insured Vehicle No :	SLF4109X	
Date of Loss:	18/12/2022	Nature of Claim:	TP	Claim No: M2207212

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC1800R	Engine No:	2ZRS063324
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Chassis No:	JTDKB3FU603563969
Reg. Date:	07/09/2017 (Man. Year: 2017)	Odometer:	803134 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 4 mm	Rear Left Side:	West Lake 4 mm
Front Right Side:	West Lake 4 mm	Rear Right Side:	West Lake 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,602.67	3,170.67	432.00	11.99
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	2,410.00	1,670.00	740.00	30.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,023.67	4,851.67	1,172.00	19.46
Approved Total (Overridden) (S\$)		3,850.00		
(S\$)	6,023.67	3,850.00	2,173.67	36.09
+ GST 7.00/7.00% (S\$)	421.66	269.50	152.16	36.09
Nett Amount (S\$)	6,445.33	4,119.50	2,325.83	36.09

INSPECTION

Date of Assignment:	20/12/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	19/12/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Jan 2023)
Parts:	144	TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC1800R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR PANEL LH	Dented	1,258.30 FL	*1,258.30 FL
2	1		*REAR FENDER PANEL LH	Dented	992.04 FL	*992.04 FL
3	1		*ROCKER PANEL GARNISH LH	Repair	576.00 FL	*- FL
4	1		*REAR WHEEL ALU.LH	Scratched	1,570.55 FL	*1,570.55 FL
5	1		*REAR DOOR COMFORT APP STICKER	Necessary	80.00 FS	*80.00 FS
6	1		*REAR FENDER PETROL STICKER	Necessary	25.00 FS	*25.00 FS
7	1		*REAR FENDER ADVERTISEMENT	Necessary	100.00 FS	*100.00 FS
8	1		*REAR DOOR ADVERTISEMENT	Necessary	100.00 FS	*100.00 FS
					Sub Total (S\$)	4,701.89
					- List Item Discount on L Items 25.00/25.00% (S\$)	1,099.22
					Total Parts (S\$)	3,602.67

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANE BEATING	New	1,300.00	900.00
2	SPRAY PAINTING	New	800.00	650.00
3	REMOVE/.REFIX UPHOLSTERY	New	90.00	40.00
4	REMOVE/.REFIX DOOR PARTS.	New	80.00	50.00
5	REMOVE./REPLACE REAR SUSPENION	New	80.00	0.00
6	TUFF COATING	New	60.00	30.00
Gross Labour Cost (\$\$)			2,410.00	1,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >