





**Bedok Motor Engineering Pte Ltd**  
 30 Defu Lane 9 Singapore 539270  
<http://www.bedokmotor.com>  
[enquire@bedokmotor.com](mailto:enquire@bedokmotor.com)  
 +65 6286 3032

*workshop@bedoktransport.com*

Estimate To Repair CB8071X GOLDEN DRA XML6772J18 AUTO

Chassis No : LL3BDADE6HA002424

| S/No                            | Quantity | Description  | Amount                   |
|---------------------------------|----------|--|--------------------------|
| <u>LIST ITEMS</u>               |          |  |                          |
| 1                               | 1pc      | Rear body panel assy   | <i>Rx</i> \$ 1,678.69    |
| 2                               | 1pc      | Rear bumper  | <i>bt</i> \$ 1,088.78    |
| 3                               | 1pc      | Rear compartment cover   | <i>Rx</i> \$ 1,157.89    |
| 4                               | 1pc      | Rear compartment cover lock  | <i>bt</i> \$ 125.68      |
| 5                               | 1pc      | Rear lamp R/h  | <i>cuad</i> \$ 250.25    |
| 6                               | 1pc      | Rear Signal light L/h top  | <i>dis</i> \$ 90.89      |
|                                 |          |  | \$ 4,392.18              |
|                                 |          |  | Less 10% \$ 439.22       |
|                                 |          |  | \$ 3,952.96              |
| <u>SPECIAL NETT ITEAMS</u>      |          |  |                          |
| 7                               | 1 pc     | Rear engine hood 60kmh sticker   | <i>all</i> \$ 20.00      |
| 8                               | 1 pc     | Rear engine hood AWC sticker   | <i>all</i> \$ 20.00      |
|                                 |          |  | \$ 40.00                 |
| <u>LABOUR &amp; MISC CHARGE</u> |          |  |                          |
| 1                               |          | To cut, weld off rear body panel assy and renew the same and renewal of the necessary parts, final checking and testing. | \$ 2,500.00 <i>1500</i>  |
| 2                               |          | Spray painting of the affected portion.  | \$ 2,000.00 <i>1000</i>  |
|                                 |          |  | \$ 4,500.00              |
|                                 |          |  | <b>Total</b> \$ 8,492.96 |

*Taufik 97495749/62563561*  
*WP' 22/12/22 @ 10am*

LKK Auto Consultants hence notify/s Resurvey after repair the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

*Resurvey after repair*  
*taufik @ lkkauto.com*  
*07 days*