

A.E.S. REC BY: Taufik

REF: CS/FC122012684/Tay3

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / IS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No: _____
Claims No: **D22003957MFBP**
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

Veh No: **668071X** Yr Regn: **2018 Aug**
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: **Golden Dragon XML67** C.C. **3759**
Colour: **white** A/C: Insured / Std / NI / NA
Sp. Reading: **99522** T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: **LL3B12ADE6HA002424**
Gen. Cond: **Good** / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or _____
Brake: In order / Jammed / Leaked / Burnt or _____
Modi: **W/S/Rim** / STD A/Rim or _____
Tyre Size: F: **215/75R17.5**
R: _____

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

| | |
|-----|-----|
| N/S | O/S |
| | |

Bal. or Market Value: **\$122k**
IDAC Accident Report _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: **7** days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT


BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or **Firestone**
Front Rear
R/Bal. **8** mm R/Bal. **8/8** mm
L/Bal. **8** mm L/Bal. **8/8** mm
D.O.A. _____ D.O.I. **22/12/22**
Survey held at **Bedok Motor**
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Roof top or _____
The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|-------------|---|
| | Taufikh confirmed lump sum: \$3150 and 7 days |
| | (red, \$5342.96, 63%) |
| | MV: \$122k-lta: \$0=\$122k |

Date/Time, File Pass to? : Preli. Report
1) **14/02/23** : Final Report
Date/Time, File Return to?
2) _____
Report Form: **tp**
Lump Sum / Lta: **3150**

Days Of Repair: **7**
Resurvey No. of Trip: **1**
Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. invs (\$ _____)
 : Wheel end (\$ _____)

Survey Fee: _____
Transportation: _____
S + RS: _____ \$
Photos: _____
Others: _____



Bedok Motor Engineering Pte Ltd
 30 Defu Lane 9 Singapore 539270
<http://www.bedokmotor.com>
enquire@bedokmotor.com
 +65 6286 3032

workshop@bedoktransport.com

Estimate To Repair CB8071X GOLDEN DRA XML6772J18 AUTO

Chassis No : LL3BDADE6HA002424

| S/No | Quantity | Description | Amount |
|---------------------------------|----------|--|--------------------------|
| <u>LIST ITEMS</u> | | | |
| 1 | 1pc | Rear body panel assy | <i>Rx</i> \$ 1,678.69 |
| 2 | 1pc | Rear bumper | <i>bt</i> \$ 1,088.78 |
| 3 | 1pc | Rear compartment cover | <i>Rx</i> \$ 1,157.89 |
| 4 | 1pc | Rear compartment cover lock | <i>bt</i> \$ 125.68 |
| 5 | 1pc | Rear lamp R/h | <i>cuad</i> \$ 250.25 |
| 6 | 1pc | Rear Signal light L/h top | <i>dis</i> \$ 90.89 |
| | | | \$ 4,392.18 |
| | | | Less 10% \$ 439.22 |
| | | | \$ 3,952.96 |
| <u>SPECIAL NETT ITEAMS</u> | | | |
| 7 | 1 pc | Rear engine hood 60kmh sticker | <i>all</i> \$ 20.00 |
| 8 | 1 pc | Rear engine hood AWC sticker | <i>all</i> \$ 20.00 |
| | | | \$ 40.00 |
| <u>LABOUR & MISC CHARGE</u> | | | |
| 1 | | To cut, weld off rear body panel assy and renew the same and renewal of the necessary parts, final checking and testing. | \$ 2,500.00 <i>1500</i> |
| 2 | | Spray painting of the affected portion. | \$ 2,000.00 <i>1000</i> |
| | | | \$ 4,500.00 |
| | | | Total \$ 8,492.96 |

Taufik 97495749/62563561
WP' 22/12/22 @ 10am

LKK Auto Consultants hence notify/s Resurvey after repair the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Resurvey after repair
taufik @ lkkauto.com
07 days