



Bedok Motor Engineering Pte Ltd
 30 Defu Lane 9 Singapore 539270
<http://www.bedokmotor.com>
enquire@bedokmotor.com
 +65 6286 3032

workshop@bedoktransport.com

Estimate To Repair CB8071X GOLDEN DRA XML6772J18 AUTO
 Chassis No : LL3BDADE6HA002424

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
1	1pc	Rear body panel assy	<i>Rp</i> \$ 1,678.69
2	1pc	Rear bumper	<i>bt</i> \$ 1,088.78
3	1pc	Rear compartment cover	<i>Rp</i> \$ 1,157.89
4	1pc	Rear compartment cover lock	<i>bb</i> \$ 125.68
5	1pc	Rear lamp R/h	<i>cuac</i> \$ 250.25
6	1pc	Rear Signal light L/h top	<i>dis</i> \$ 90.89
			1555.60
			1400.04
			Less 10%
			\$ 4,392.18
			\$ 439.22
			\$ 3,952.96
<u>SPECIAL NETT ITEAMS</u>			
7	1 pc	Rear engine hood 60kmh sticker	<i>all</i> \$ 20.00
8	1 pc	Rear engine hood AWC sticker	<i>all</i> \$ 20.00
			40
			\$ 40.00
<u>LABOUR & MISC CHARGE</u>			
1		To cut, weld off rear body panel assy and renew the same and renewal of the necessary parts, final checking and testing.	\$ 2,500.00 <i>1500</i>
2		Spray painting of the affected portion.	\$ 2,000.00 <i>1000</i>
			<i>2500</i>
			\$ 4,500.00
			Total
			\$ 8,492.96

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Taufik 97495749/62563561
WP' 22/12/22 @ 10am

Resurvey after repair
taufik@lkkauto.com
07 days

1400.04
40
2500

3940.04
1/5 @ 3150, 7 days
#