



Bedok Motor Engineering Pte Ltd
 30 Defu Lane 9 Singapore 539270
<http://www.bedokmotor.com>
enquire@bedokmotor.com
 +65 6286 3032

Estimate To Repair CB8071X GOLDEN DRA XML6772J18 AUTO

Chassis No : LL3BDADE6HA002424

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
1	1pc	Rear body panel assy	\$ 1,678.69
2	1pc	Rear bumper	\$ 1,088.78
3	1pc	Rear compartment cover	\$ 1,157.89
4	1pc	Rear compartment cover lock	\$ 125.68
5	1pc	Rear lamp R/h	\$ 250.25
6	1pc	Rear Signal light L/h	\$ 90.89
			\$ 4,392.18
Less 10%			\$ 439.22
			\$ 3,952.96
<u>SPECIAL NETT ITEAMS</u>			
7	1 pc	Rear engine hood 60kmh sticker	\$ 20.00
8	1 pc	Rear engine hood AWC sticker	\$ 20.00
			\$ 40.00
<u>LABOUR & MISC CHARGE</u>			
1		To cut, weld off rear body panel assy and renew the same and renewal of the necessary parts, final checking and testing.	\$ 2,500.00
2		Spray painting of the affected portion.	\$ 2,000.00
			\$ 4,500.00
Total			\$ 8,492.96