

08/11/23 Wef
ASS. REC. BY: Form

REF: CS/SMR22012686/Rng3

621K

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLG 4281A

at Workshop n/s LCR

of 4, JLN B&SW

Insured: SMR

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 50K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

REPAIR LIMIT - 22K

Veh No: SLG 4281A Yr Regn: 2016 / SEP

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MAZDA3 SEDAN / SLR c.c 1496

Colour: BLUE A/C: Insured / Std / NI / NA

Sp. Reading: 44996 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6BM 42A840346570

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: 2

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or RYDANZ

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 18/12/22

D.O.I. 20/12/22

Survey held at LCR

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

N/S FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

) S + RS SI

) Photos

) Others

Report Format : _____

Lump Sum / I.B.I. (\$) _____

TOTAL




LION CITY RENTALS PTE LTD
4 Jalan Besut S(619557)

SMRT

Date : 19-Dec-22

Attn : MOTOR CLAIMS DEPT

VEHICLE NO. : SLG4281A
CHASSIS NO. : JM6BM42A8G0346570
MAKE / MODEL : Mazda 3
DATE OF
ACCIDENT: 18-Dec-22
YOUR INSURED VEHICLE NUMBER : SMB1596B



<u>PARTS DISCRIPTION</u>			<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	FRONT BUMPER <i>de</i>		1PC	\$1,020.00	\$1,020.00
2	FRONT BUMPER RETAINER <i>sea</i>	LH	1PC	\$89.00	\$89.00
3	FRONT HEADLAMP ?	LH	1PC	\$825.00	\$825.00
4	FRONT FENDER <i>bt</i>	LH	1PC	\$495.00	\$495.00
5	FRONT FOGLAMP <i>X</i>	LH	1PC	\$130.50	\$130.50
6	FRONT FOGLAMP COVER <i>X</i>	LH	1PC	\$48.60	\$48.60
7	FRONT FENDER UNDER-DUSCT COVER <i>can</i>	LH	1PC	\$139.50	\$139.50
8	FRONT GRILLE ASSY <i>can</i>		1PC	\$304.50	\$304.50
9	FRONT BUMPER UNDER-DUST COVER <i>can</i>		1PC	\$145.00	\$145.00
10	FRONT GRILLE INNER BRACKET ?	LH	1PC	\$420.00	\$420.00
Total					\$3,617.10
Less 20%					\$723.42
Total					\$2,893.68

<u>SPECIAL NETTS</u>		<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	FRONT BUMPER CLIPS <i>sea</i>	1	\$ 40.00	\$ 40.00 <i>430</i>
2	FRONT FENDER UNDER-DUSCT COVER CLIPS <i>sea</i>	1	\$ 40.00	\$ 40.00 <i>30</i>
Total				\$ 80.00

<u>LABOUR CHARGES</u>		
1	REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT / WELD, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS.	\$ 1,000.00 <i>500</i>
2	PUTTY AND SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER)	\$ 800.00 <i>400</i>
3	TO REMOVE, REARRANGE ELECTRICAL WIRING, CHECK LIGHTING & RESET HEADLAMP FOCUSING	\$ 180.00 <i>130</i>
4	COMPUTERIZED ALIGNMENT	\$ 120.00 <i>60</i>

TOTA
TOTAL PARTS
GRAND TOTAL

\$	2,100.00
\$	2,973.68
\$	5,073.68

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasue
Hp 90010068
4 days
L/S
20/2/22 @1440
Resurvey after
repair

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	621K
Vehicle Details	
Vehicle No.:	SLG4281A
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Dec 2022
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP6EAT
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	P520375610
Chassis No.:	JM6BM42A8G0346570
Maximum Power Output:	88.0kW (118 bhp)
Open Market Value:	\$16,738.00
Original Registration Date:	29 Sep 2016
First Registration Date:	29 Sep 2016
Transfer Count:	2
Actual ARF Paid:	\$11,738.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Sep 2026
PARF Rebate Amount:	\$7,629.00
Intended COE Rebate Details	
COE Expiry Date:	28 Sep 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$58,201.00
COE Rebate Amount:	\$19,790.00
Total Rebate Amount:	\$27,419.00

The information contained herein is correct as at 21 Dec 2022

Mazda 3 1.5A Sunroof

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price

\$50,800

Depreciation ⓘ

\$11,910 /yr

[View models with similar depre](#)

Reg Date

29-Sep-2016

(3yrs 9mths 7days COE left)

Mileage

N.A.

Manufactured ⓘ

2016

Road Tax ⓘ

\$682 /yr

Transmission

Auto

Dereg Value ⓘ

\$27,417 as of today (change)

OMV ⓘ

\$16,738

COE ⓘ

\$58,201

ARF ⓘ

\$11,738

Engine Cap

1,496 cc

Power

88.0 kW (118 bhp)

Curb Weight ⓘ

1,321 kg

No. of Owners ⓘ

4

Type of Vehicle

Mid-Sized Sedan