



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|--|-----------------|--|--|
| HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:GARNET | | | Ref: CC4/ASM22012688/Upa3q2 Date: 03/04/2023 Code: HSB | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | SHD 9474R | Veh. Inspected | FBR 7125J | |
| Policy No. | P2477626 | Coverage (\$) | 0.00 | |
| Claim No. | S2M04FZO | Excess (\$) | 0.00 | |
| Assign From | | Assign Date | 20/12/2022 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | YAMAHA AEROX GDR155 | c.c | 155 | |
| Engine No. | HIDDEN | Year of Reg. | 2020 | |
| Chassis No. | MH3SG4610LJ334804 | Colour | GREEN | |
| Odometer | 50825 KM | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | SPORTS RIM | |
| General | GOOD | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 110/80-14 | PIRELLI | 6 mm | |
| L/H Front Tyre | | | mm | |
| R/H Rear Tyre | 140/70-14 | PIRELLI | 6 mm | |
| L/H Rear Tyre | | | mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S & N/S BODY. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 03/12/2022 | Inspection Date | 20/12/2022 | |
| Survey held at | 2ND AUTO PTE LTD 15 KAKI BUKIT ROAD 4, #01-53, BARTLEY BIZ CENTRE, SINGAPORE 417808 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | | 4 Working Days | |